

Homestead Entry Survey No. 141
 Metes and Bounds Survey of Ben Williams, Homestead Entry
 Umpqua National Forest, Oregon.

CHAINS

IMPROVEMENTS

The improvements on this claim, the property of the claimant herein, consist of the following:

Log house, 12 x 24 ft., course of long sides, E. and W., the SW. cor. of which bears from Cor. 7, N. 62°15' E., 7.30 chs. dist.
 Value, \$50.00.

Log barn, 26 x 30 ft., course of long sides, N. and S., the SW. cor. of which bears from Cor. 7, N. 67°00' E., 5.70 chs. dist.
 Value, \$250.00.

Log smokehouse, 8 x 9 ft., course of long sides E. and W., the SW. cor. of which bears, from Cor. 7, N. 65°00' E., 8.10 chs. dist.
 Value, \$50.00.

Log roothouse, 10 x 10 ft., course of sides, N. S., E. and W., the SW. cor. of which bears, from Cor. 7, N. 67°45' E., 7.30 chs. dist.
 Value, \$40.00.

Log chickenhouse, 10 x 10 ft., course of sides, N., S., E. and W., the SW. cor. of which bears, from Cor. 7, N. 55°35' E., 10.60 chs. dist.
 Value, \$35.00.

About 110 rods of pole fencing.
 Value, \$44.00.

Total value of improvements - \$469.00.

DESCRIPTION.

The principal part of this claim lies along Deadman Creek bottom; The conjunction of the North and West forks of the creek occurring about the center of the claim. The soil is a deep, sandy loam, 1st rate. A portion of the claim along the boundaries lies on rolling land, along the foot of the mountains. This is a humus soil, with a clay subsoil, 2nd rate. The entire claim; except the cultivated land; is heavily timbered with pine, fir, and cedar on the rolling land, while the bottom land is covered with maple, ash, alder and cottonwood timber and a dense undergrowth of vine maple, willows and seven-bark. About 16 acres of the land within this claim are under cultivation. The claim is surrounded by heavy timber of an all-age stand. The land is non-mineral in character.

The claim is situated about 9 miles in a northeast direction from Tiller, Oregon, the nearest post office, and connected by a trail.

REMARKS

The road exemption through a portion of this claim was simplified as shown by the plat and field notes, and was changed by full knowledge and consent of the claimant, to make the initial and terminal points more accessible and to better serve its purpose, and in addition will preserve the locus of Cor. H/5 and Cor. H/6 of listing survey, which are identical with Cors. 10 and 16 of this survey, and would otherwise fall in the center of the road and eventually be destroyed.

Authority is based on G. L. O. letters dated February 4 and March 30, 1914.

The road was located as follows:

After I determined the courses of lines 7-8 and 10-16 I located the initial and terminal points for the center of this road at a point on these angles that would make the road 45½ lks. right angle