

County Surveyor's Record, Douglas County, Oregon

11768

Dependent Resurvey of Sec. 9, T. 29 S., R. 7 W.

CHAINS

*FD OK
5/19/81
H. JOHNSON
M 97-75*

T 29 S R 7 W
S 9 S 10
S 16 S 15
1955

from which new bearing trees

A fir, 12 ins. diam., bears N. $64\frac{1}{2}^\circ$ E., 38 lks. dist.,
marked T 29 S R 7 W S 10 BT.

A fir, 18 ins. diam., bears S. 68° E., 62 lks. dist.,
marked T 29 S R 7 W S 15 BT.

A fir, 43 ins. diam., bears S. $61^\circ 45'$ W., 84 lks. dist.,
marked T 29 S R 7 W S 16 BT.

A fir, 36 ins. diam., bears N. $22\frac{1}{4}^\circ$ W., 24 lks. dist.,
marked T 29 S R 7 W S 9 BT.

N. $6^\circ 10'$ E., bet. secs. 9 and 10.

Descend 211 ft. over NW. slope, through timber and undergrowth.

10.06 Branch, 2 lks. wide, course NW.; asc. 256 ft. over SW. slope.

18.53 Point for the south 1/16 sec. cor. of secs. 9 and 10.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground,
with brass cap marked

S 1/16
S 9 S 10
1955

from which

A fir, 9 ins. diam., bears N. $58\frac{1}{2}^\circ$ E., 14 lks. dist.,
marked S 1/16 S 10 BT.

A fir, 20 ins. diam., bears S. $78\frac{1}{2}^\circ$ W., 12 lks. dist.,
marked S 1/16 S 9 BT.

Ascend 60 ft. over SW. slope.

23.62 Spur, slopes W.; desc. 303 ft. over NW. slope.

37.06 Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 10, at proportionate
distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground,
with brass cap marked

$\frac{1}{4}$
S 9 S 10
1955

from which

A fir, 14 ins. diam., bears N. $75\frac{1}{2}^\circ$ E., 90 lks. dist.,
marked $\frac{1}{4}$ S 10 BT.

A fir, 32 ins. diam., bears N. 14° W., 67 lks. dist.,
marked $\frac{1}{4}$ S 9 BT.

Descend 62 ft. over N. slope.

39.68 Branch, 2 lks. wide, course W.; asc. 358 ft. over S. slope.

55.59 Point for the north 1/16 sec. cor. of secs. 9 and 10.