

11774 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Sec. 9, T. (27) S., R. 7 W.

CHAINS

A fir, 10 ins. diam., bears S. $50\frac{1}{2}^\circ$ E., 51 lks. dist.,
marked L 1 T 29 S R 7 W S 9 CC BT.

From this corner the point for the NE. corner of donation land claim No. 41 bears North, 31.70 chs. dist., located by record ties; there is no remaining evidence of the original corner.

From the same corner the point for the SE. corner of donation land claim No. 41 bears South, 3.60 chs. dist., located by record ties; there is no remaining evidence of the original corner.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

$$\begin{array}{r} \text{C 41} \\ \hline 1 \\ \text{S 9} \\ 1955 \end{array}$$

from which

A fir, 8 ins. diam., bears N. 88° E., 22 lks. dist.,
marked L 1 S 9 BT.

A fir, 15 ins. diam., bears S. 57° W., 26 lks. dist.,
marked L 1 S 9 BT.

19.40 Set temp. east $\frac{1}{16}$ sec. cor. of secs. 4 and 9.

38.80 The $\frac{1}{4}$ sec. cor. of secs. 4 and 9, determined at record bearing and distance from a bearing tree marked by the County Surveyor in 1890.

A white oak, 36 ins. diam., bears N. 73° W., 244 lks. dist.,
with marks BT uncovered.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 35 ins. in the ground, with brass cap marked

$$\begin{array}{r} \frac{1}{4} \text{ S } 4 \\ \hline 4 \text{ S } 9 \\ 1955 \end{array}$$

from which new bearing trees

A white oak, 8 ins. diam., bears N. 44° E., 352 lks. dist.,
marked $\frac{1}{4}$ S 4 BT.

A white oak, 14 ins. diam., bears S. 11° W., 227 lks. dist.,
marked $\frac{1}{4}$ S 9 BT.

N. $88^\circ 04'$ W., beginning new measurement.

20.22 Set temp. west $\frac{1}{16}$ sec. cor. of secs. 4 and 9.

40.44 The cor. of secs. 4, 5, 8 and 9.

Land, mountainous in the east half and level in the west half.
Soil, rocky clay.
Timber, fir, oak, maple and madrona.
Undergrowth, vine maple, arrowwood, poison oak and fern.