

# 11776 County Surveyor's Record, Douglas County, Oregon

Portion of the Subdivisional Lines of Sec. 9, T. 29 S., R. 7 W.

CHAINS

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

C  $\frac{E \ 1/16}{S \ 9}$  C  
1955

from which

A fir, 10 ins. diam., bears N. 8° E., 12 lks. dist., marked CE 1/16 S 9 BT.

A fir, 15 ins. diam., bears S. 76° E., 87 lks. dist., marked CE 1/16 S 9 BT.

Ascend 294 ft. over NE. slope.

34.84 Spur, slopes N.; desc. 116 ft. over NW. slope.

39.00 The center  $\frac{1}{4}$  sec. cor. of sec. 9.

Descend 122 ft. over NW. slope.

47.61 Ravine, drains N.; asc. 214 ft. over E. slope.

57.06 Point for the center west 1/16 sec. cor. of sec. 9.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

C  $\frac{W \ 1/16}{S \ 9}$  C  
1955

from which

A fir, 8 ins. diam., bears N. 10 $\frac{1}{2}$ ° E., 13 lks. dist., marked CW 1/16 S 9 BT.

A fir, 9 ins. diam., bears S. 16 $\frac{1}{4}$ ° E., 29 lks. dist., marked CW 1/16 S 9 BT.

Ascend 80 ft. over E. slope.

60.61 Spur, slopes NE.; desc. 145 ft. over NW. slope.

71.70 Draw, drains N.; asc. 25 ft. over NE. slope.

75.12 The  $\frac{1}{4}$  sec. cor. of secs. 8 and 9.

Land, mountainous.

Soil, rocky clay.

Timber, fir, oak, maple and madrona.

Undergrowth, vine maple, arrowwood, poison oak and fern.

From the center east 1/16 sec. cor. of sec. 9.

N. 6°18' E., along the N. and S. center line of the NE  $\frac{1}{4}$  of sec. 9.

Through timber and undergrowth.

18.80 Point for the northeast 1/16 sec. cor. of sec. 9, at intersection with E. and W. center line of the NE  $\frac{1}{4}$ .

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

NE 1/16 S 9  
1955

from which