

12078 County Surveyor's Record, Douglas County, Oregon

4

HOMESTEAD ENTRY SURVEY NO. 213
 SIUSLAW NATIONAL FOREST
 STATE OF OREGON

CHAINS

August 31, 1917: Commencing at meander cor. and cor. No. 1 of this survey, identical with the meander cor. bet. fractional secs. 6 and 1, T. 22 S., Rs. 10 and 11 W., heretofore described.

Set a maple post, 60 ins. long, 5 ins. square, 48 ins. in the ground, alongside meander cor. for fractional secs. 6 and 1, marked 1 HES 213 on side facing the claim and M C on side facing Umpqua River, as a marker for cor. No. 1 of this survey. Set a post as cor. falls in soft mud adjacent to tide flats. The cor. of secs. 1 and 12, T. 22 S., R. 11 W., hereinbefore described, bears S.0°02'W., 17.30 chs.

Thence I run

S.0°02'W., on a true line, along range line bet. fractional secs. 6 and 1 as determined by my retracement, heretofore described.

Over level open land.

4.50 Begin ascent of steep north slope through undergrowth.

4.64 Cor. No. 2 and closing cor. 20 ft. above cor. No. 1, on range line bet. fractional secs. 6 and 1 and on the prolongation of the line bet. cors. No. 12 and No. 13 of the listing survey.

Set a sandstone, 26x10x10 ins., 16 ins. in the ground, over a stone marked with a cross, for closing cor. and cor. No. 2 of this survey, marked C C on west face and 2 HES 213 on side facing the claim; from which

A fir, 14 ins. dia., bears S.64°30'E., 37 lks. dist., marked X 2 HES 213 C C B T.

A spruce, 6 ins. dia., bears N.20°30'W., 18 lks. dist., marked X 2 HES 213 C C B T.

Cor. is on steep north slope; mounds impracticable.

The cor. of secs. 1 and 12, T. 22 S., R. 11 W., heretofore described, bears S.0°02'W., 12.66 chs. distant.

From cor. No. 13 of listing survey, I run

N.80°00'W., on a random line, and at 5.67 chs. fall 18-3/4 lks. S.10°00'W. of cor. No. 12 of listing survey.

(The true bearing and length of this line is N.78°06'W., 5.67 chs.)

Returning to cor. No. 2 of this survey, above described, I run

N.78°06'W., on a true line.

Along base of steep north slope, through dense undergrowth.

0.10 Cor. No. 13 of listing survey, which I destroy.

5.77 Cor. No. 3, identical with cor. No. 12 of listing survey, which I destroy, and in its place

Set a sandstone slab, 26x14x3 ins., 16 ins. in the ground, over a stone marked with a cross for cor. No. 3 of this survey, marked 3 H E S 213 on side facing the claim; from which

A spruce, 5 ins. dia., bears S.68°30'W., 8 lks. dist., marked X 3 H E S 213 B T.

A fir, 8 ins. dia., bears S.10°00'E., 6 lks. dist., marked X 3 H E S 213 B T.