

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 7 W.

CHAINS

A fir, 9 ins. diam., bears N. 47° E., 180 lks. dist.,
marked T29S R7W S12 BT.

A fir, 9 ins. diam., bears S. 33° E., 93 lks. dist.,
marked T29S R7W S13 BT.

A fir, 8 ins. diam., bears S. 32° W., 78 lks. dist.,
marked T29S R7W S14 BT.

A fir, 11 ins. diam., bears N. 73° W., 83 lks. dist.,
marked T29S R7W S11 BT.

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, maple,
chinquapin and alder. Undergrowth, vine maple, hazel, arrowwood,
Oregon grape and fern.

From the cor. of secs. 7, 12, 13 and 18 on E. bdy. of Tp.

N. 86° 40' W., bet. secs. 12 and 13.

Descend 20 ft. over NW. slope through heavy timber and dense under-
growth.

0.50 Branch, 3 lks. wide, course NW.; descend 10 ft. over broken N.
slope.

4.60 Branch, 3 lks. wide, course N.; ascend 30 ft. over NE. slope.

8.00 Spur, slopes N.; descend 220 ft. over broken NW. slope.

19.00 Graveled road, 20 lks. wide, bears N. and S. 30° W.

21.00 Kent Creek, 10 lks. wide, course N. 30° E.; ascend 600 ft. over E.
slope.

43.15 Point for the $\frac{1}{4}$ sec. cor. of secs. 12 and 13, at proportionate dis-
tance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground,
with brass cap marked

T29S R7W
S 12
 $\frac{1}{4}$ ———
S 13
1957

from which

A fir, 6 ins. diam., bears N. 7° E., 110 lks. dist.,
marked $\frac{1}{4}$ S12 BT.

A fir, 18 ins. diam., bears S. 41° W., 106 lks. dist.,
marked $\frac{1}{4}$ S13 BT.

Ascend 180 ft. over E. slope, changing to NE. slope.

53.00 Spur ridge, bears NE. and SW.; descend 150 ft. over NW. slope.

66.00 Head of ravine, course N.; ascend 300 ft. over broken NE. slope.

86.30 The cor. of secs. 11, 12, 13 and 14.

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, maple,
madrona and alder. Undergrowth, vine maple, hazel, arrowwood,
Oregon grape and fern.

N. 0° 55' W., bet. secs. 11 and 12.