

County Surveyor's Record, Douglas County, Oregon

9

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 7 W.

CHAINS

A white oak, 12 ins. diam., bears S. 50° W., 100 lks. dist.,
with partial scribe marks visible on opened blaze.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground,
with brass cap marked

T29S R7W
↑
S 10 | S 11
1957

from which new bearing trees,

A fir, 30 ins. diam., bears S. 49½° E., 75 lks. dist.,
marked ¼ S11 BT.

A fir, 12 ins. diam., bears N. 43° W., 141 lks. dist.,
marked ¼ S10 BT.

N. 0° 44' E., beginning new measurement.

Ascend 30 ft. along broken W. slope.

11.50 Spur, slopes N. 70° W.; descend 280 ft. over broken NW. slope.

20.90 Wet ravine, drains N. 70° W.; ascend 190 ft. over SW. slope.

36.35 Spur, slopes S. 80° W.; descend 70 ft. over NW. slope, changing to
W. slope.

39.05 The cor. of secs. 2, 3, 10 and 11, remonumented by the County Sur-
veyor in 1923 with a sandstone, 15x10x8 ins., now shattered with no
marks remaining, from which the remaining original bearing trees:

A white oak, 30 ins. diam., bears N. 15° E., 62 lks. dist.,
plainly blazed and healed.

A fallen white oak, 26 ins. diam., bears S. 25° W., 105 lks.
dist., with partial scribe marks visible on unhealed blaze.

A white oak, 38 ins. diam., bears N. 45° W., 50 lks. dist.,
plainly blazed and healed.

and a tree marked in 1923:

A white oak, 10 ins. diam., bears S. 50° E., 16 lks. dist.,
plainly blazed and healed.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground,
with brass cap marked

T29S R7W
S 3 | S 2
S 10 | S 11
1957

from which a new bearing tree,

A fir, 8 ins. diam., bears S. 53° W., 81 lks. dist.,
marked T29S R7W S10 BT.

Deposit the shattered sandstone at the base of the iron post as a
memorial.