

County Surveyor's Record, Douglas County, Oregon

10

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 7 W.

CHAINS

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, pine, oak, maple, hazel, arrowwood, poison oak and fern.

From the cor. of secs. 1, 2, 11 and 12.

S. 88° 49' W., bet. secs. 2 and 11.

Descend 110 ft. over NW. slope through scattering timber and dense undergrowth.

2.75 Branch, 2 lks. wide, course S. 70° W. at bend from the NE.; descend 340 ft. along broken S. slope.

42.83 The $\frac{1}{4}$ sec. cor. of secs. 2 and 11, remonumented by the County Surveyor in 1923 with a basalt stone, 12x6x6 ins., marked $\frac{1}{4}$ on W. face, firmly set 6 ins. in the ground, from which bearing trees marked by the County Surveyor:

A fir, 15 ins. diam., bears S. 57 $\frac{1}{2}$ ° E., 33 lks. dist., plainly blazed and healed.

A fir, 24 ins. diam., bears S. 72° W., 26 lks. dist., marked BT on partly opened blaze.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

T29S R7W

$\frac{1}{4}$ S 2
S II

1957

from which a new bearing tree,

A fir, 12 ins. diam., bears N. 32° W., 61 lks. dist., marked $\frac{1}{4}$ S2 BT.

Reset the basalt stone alongside the iron post.

The $\frac{1}{4}$ sec. cor. falls on a spur, slopes SW.; edge of heavy timber bears N. and S.

S. 88° 25' W., beginning new measurement.

Descend 60 ft. over W. slope through heavy timber and dense undergrowth.

1.80 Ravine, course S. 30° W.; descend 60 ft. along broken S. slope.

16.40 Graded road, 15 lks. wide, bears NW. and SE.

18.00 McNabb Creek, 5 lks. wide, course NW.; ascend 480 ft. over NE. slope.

34.50 Ridge, bears NW. and SE.; descend 240 ft. over W. slope.

41.67 The cor. of secs. 2, 3, 10 and 11.

Land, mountainous. Soil, rocky clay. Timber, fir, oak, pine, cedar, madrona and maple. Undergrowth, poison oak, hazel, arrowwood, vine maple and fern.

From the cor. of secs. 14, 15, 22 and 23.

N. 85° 47' W., bet. secs. 15 and 22.