

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of the Subdivisional Lines of T. 29 S., R. 7 W.

CHAINS

T29S R7W
 S 17 | S 16
 S 20 | S 21
 1957

from which new bearing trees,

A fir, 8 ins. diam., bears N. 72° E., 114 lks. dist., marked T29S R7W S16 BT.

A fir, 17 ins. diam., bears S. 13° W., 190 lks. dist., marked T29S R7W S20 BT.

Reset County Surveyor's monument alongside the iron post.

Land, mountainous. Soil, rocky clay. Timber, fir, cedar, madrona, oak, and pine. Undergrowth, hazel, poison oak, Oregon grape, arrowwood and fern.

N. 1° 45' E., bet. secs. 15 and 16.

Descend 220 ft. over broken N. slope through heavy timber and dense undergrowth.

17.05 Branch, 5 lks. wide, course W.; ascend 450 ft. over general S. slope.

39.93 Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

T29S R7W
 ↑
 S 16 | S 15
 1957

from which

A fir, 15 ins. diam., bears N. 53° E., 74 lks. dist., marked $\frac{1}{4}$ S15 BT.

A fir, 16 ins. diam., bears S. 58° W., 52 lks. dist., marked $\frac{1}{4}$ S16 BT.

This $\frac{1}{4}$ sec. cor. is located on a spur, slopes SW.; descend 130 ft. over NW. slope.

47.30 Head of ravine, drains S. 70° W.; ascend 190 ft. over SW. slope.

57.80 Ridge, bears NW. and SE.; descend 400 ft. over broken NE. slope.

79.86 The cor. of secs. 9, 10, 15 and 16, monumented with an iron post, 2 ins. diam., 8 ins. above ground, firmly set, marked and witnessed as described in the official record.

Land, mountainous. Soil, rocky clay loam. Timber, pine, fir, cedar, oak and madrona. Undergrowth, vine maple, hazel, poison oak and fern.

From the cor. of secs. 10, 11, 14 and 15.

N. 84° 26' W., bet. secs. 10 and 15.

Descend 200 ft. over NW. slope through heavy timber and dense undergrowth.

10.80 Branch, 3 lks. wide, course N. 15° E.; asc. 370 ft. over E. slope.