

County Surveyor's Record, Douglas County, Oregon

Homestead Entry Survey No. 93, T. 26 S., R. 2 E.

CHAINS	
	<p>A fir, 24 ins. diam., bears S. 15° 15' E., 161 lks. dist., blazed and scribed 3 HES 93 BT.</p> <p>A basalt boulder, 3 ft. E. and W., 2 ft. N. and S., 1 ft. high, mkd. BR with cross (+) bears S. 57° 08' W., 32 lks. dist.</p> <p>Land, rolling. Timber, pine and fir. Soil, very stony, 2nd rate. Pits and mound impracticable at this and all other courses.</p> <hr/> <p>Thence, N. 87° 40' W., on true line to Cor. No. 4. Over rolling land, through scattering timber and undergrowth.</p>
3.76	Creek, 5 lks. wide, course S.
14.50	Forest Service Trail, bears NE. and SW.
15.10	<p>To Cor. No. 4, identical with Cor. H/3 of listing survey, a post mkd. and witnessed as described by Asher Ireland, Assistant Forest Ranger, in place of which I set a basalt stone, 24x10x6 ins., 14 ins. in the ground, for Cor. 4, mkd. 4 HES 93 on NE. face, with a cross on top, from which</p> <p>A fir, 30 ins. diam., bears S. 50° 15' E., 72 lks. dist.,</p> <p>A fir, 15 ins. diam., bears N. 17° 10' W., 89 lks. dist., both trees blazed and scribed 4 HES 93 BT.</p> <p>Land, rolling. Timber, pine and fir. Soil, stony, 2nd rate.</p> <hr/> <p>Thence, N. 9° 45' W., on true line to Cor. 5. Over rolling land, through scattering timber and undergrowth.</p>
1.12	Dry ravine, course S.
2.50	Leave rolling and enter mountainous land, bears NE. and SW.; enter undergrowth, bears NE. and SW. Ascend.
7.55	Same ravine, course SE.
8.00	Trail, bears E. and W.
24.40	<p>To Cor. No. 5, identical with Cor. H/4 of listing survey, 430 ft. above point asc., a post mkd. and witnessed as described by Asher Ireland, Assistant Forest Ranger, in place of which, I set a basalt stone, 24x10x8 ins., 14 ins. in the ground, for Cor. 5, mkd. 5 HES 93 on SE. face, with cross (+) on top, from which</p> <p>A fir, 36 ins. diam., bears N. 66° 30' E., 175 lks. dist., blazed and scribed 5 HES 93 BT.</p> <p>No other trees within limits. I raise a mound of stone, 3 ft. base, 2 ft. high, SE. of cor.</p> <p>Land, rolling and mountainous. Timber, pine and fir. Soil, very stony, 3rd rate.</p> <hr/> <p>Thence, S. 88° 44' E. on true line to Cor. 6. Over mountainous land, through scattering timber and dense undergrowth.</p>
1.50	Top of main ridge, bears NW. and SE., 15 ft. above Cor. 5. Descend.
11.96	Creek, 5 lks. wide, course SE., 280 ft. below top of ridge. Asc.
19.95	To Cor. 6, 175 ft. above creek; identical with Cor. H/5 of listing survey, a post, mkd. and witnessed as described by Asher Ireland, Assistant Forest Ranger; in place of which I set a basalt stone,