

County Surveyor's Record, Douglas County, Oregon

10

Dependent Resurvey of Portion of Subdivisional Lines, T. 25 S., R. 4 W.

CHAINS

with brass cap marked

T25S R4W	
S 26	S 25
S 35	S 36
1957	

from which

A cedar, 15 ins. diam., bears N. 35° 45' E., 97 lks. dist., marked T25S R4W S25 BT.

A fir, 41 ins. diam., bears S. 56° E., 60 lks. dist., marked T25S R4W S36 BT.

A cedar, 27 ins. diam., bears S. 17½° W., 113 lks. dist., marked T25S R4W S35 BT.

A cedar, 15 ins. diam., bears N. 10° W., 120 lks. dist., marked T25S R4W S26 BT.

Reset the iron pipe alongside the iron post.

The corner falls at a fence corner with fences extending E. and S.

Land, mountainous. Soil, clay and loam. Timber, fir, cedar, hemlock, and pine; undergrowth, salal, vinemaple, madrone, scrub oak, and poison oak.

From the cor. of secs. 25, 30, 31 and 36 on the E. bdy. of the Tp. S. 89° 10' W., bet. secs. 25 and 36.

Ascend 246 ft. over NE. slope, through heavy timber and dense undergrowth.

0.77 Dirt logging road, 25 lks. wide, bears N. and S.

7.60 Ridge, bears N. and S.; descend 224 ft. over NW. slope.

8.12 Dirt logging road, 30 lks. wide, bears N. and S.

21.15 Skid road, 20 lks. wide, bears NE. and SW.

21.695 Point for the E 1/16 sec. cor. of secs. 25 and 36.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

E 1/16 S 25	
S 36	
1957	

from which

A cedar, 20 ins. diam., bears N. 64½° W., 29 lks. dist., marked E 1/16 S25 BT.

A fir, 10 ins. diam., bears S. 60° W., 27 lks. dist., marked E 1/16 S36 BT.

Descend 145 ft. over NW. slope.

23.60 Woven-wire fence, bears N. and S.

31.04 Spring branch, 4 lks. wide, course S.; ascend 28 ft. over broken SE. slope.

43.39 The ¼ sec. cor. of secs. 25 and 36, a rotted fir stump, 12 ins. diam., marked on E. face by the county surveyor with illegible scribe marks visible on rotted blaze, from which the remains of the original bearing trees:

A fir stump, 24 ins. diam., bears N. 60° W., 8 lks. dist., with