

## County Surveyor's Record, Douglas County, Oregon

11

Dependent Resurvey of Portion of Subdivisional Lines, T. 25 S., R. 4 W.

CHAINS

no scribe marks visible on old rotted and burned blaze.

A fir stump, 20 ins. diam., bears S. 40° E., 4 lks. dist., with no scribe marks visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked

T25S R4W

 $\frac{1}{4}$  S 25 $\frac{1}{4}$  S 36

1957

from which

A madrone, 6 ins. diam., bears N. 51° W., 68 lks. dist., marked  $\frac{1}{4}$  S 25 BT.A madrone, 8 ins. diam., bears S. 73° E., 166 lks. dist., marked  $\frac{1}{4}$  S 36 BT.

Deposit the fir stump alongside the iron post.

The cor. falls by a fence extending N. and S. on spur, sloping S.

S. 88° 15' W., beginning new measurement.

Descend 162 ft. over W. slope.

3.90 Huntley Creek, 10 lks. wide, course S.; ascend 176 ft. over SE. slope.

15.37 Spur, slopes S.; descend 25 ft. over SW. slope.

19.84 Point for the W 1/16 sec. cor. of secs. 25 and 36.

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked

W 1/16  $\frac{S}{S}$   $\frac{25}{36}$ 

1957

from which

A fir, 13 ins. diam., bears N. 43° E., 55 lks. dist., marked W 1/16 S25 BT.

An oak, 5 ins. diam., bears S. 72° E., 91 lks. dist., marked W 1/16 S36 BT.

The corner falls at the W. edge of logged area, bears N. and S.

Descend 75 ft. over SW. slope.

28.02 Creek, 3 lks. wide, course S. 70° E.; ascend 347 ft. over NE. slope.

28.84 Dirt logging road, 15 lks. wide, bears NW. and SE.

39.68 The cor. of secs. 25, 26, 35 and 36.

Land, mountainous. Soil, clay and loam. Timber, fir, hemlock, maple, cedar, madrone and pine; undergrowth, vinemaple, hazel, and fir reproduction.

N. 3° 08' E., bet. secs. 25 and 26.

Descend 151 ft. over N. slope, through heavy timber and dense undergrowth.