

County Surveyor's Record, Douglas County, Oregon

25

Dependent Resurvey of Portion of Subdivisional Lines, T. 25 S., R. 4 W.

CHAINS

T25S R4W

 $\frac{1}{4}$ S 23 $\frac{1}{4}$ S 26

1957

from which

A fir, 31 ins. diam., bears N. 37° W., 53 lks. dist., marked $\frac{1}{4}$ S23 BT.A cedar, 5 ins diam., bears S. 14° W., 40 lks. dist., marked $\frac{1}{4}$ S26 BT.

Deposit local corner stake alongside iron post.

S. 88° 12' W., beginning new measurement.

Descend 43 ft. over NW. slope, through scattering timber and undergrowth.

2.23 Creek, 1 lk. wide, course N. 30° E.; ascend 274 ft. over E. slope.

11.74 Spur ridge, bears N. and S. 15° E., enter prairie, edge bears same as ridge; descend 279 ft. over W. slope.

17.91 Leave prairie, enter logged area, edge bears NE. and SW.

19.215 Point for the W 1/16 sec. cor. of secs. 23 and 26.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap markedW 1/16 $\frac{S}{S}$ $\frac{23}{26}$

1957

from which

A fir, 33 ins. diam., bears N. 24 $\frac{1}{4}$ ° E., 58 $\frac{1}{2}$ lks. dist., marked W 1/16 S23 BT.A fir, 33 ins. diam., bears S. 66 $\frac{1}{2}$ ° W., 65 lks. dist., marked W 1/16 S26 BT.

Descend 511 ft. over W. slope.

28.05 Skid road, 15 lks. wide, bears NW. and SE.

32.28 Same skid road, 15 lks. wide, bears NE. and SW.

34.03 Skid road, 15 lks. wide, bears N. 30° W. and S. 30° E.

35.10 Markham Creek, 4 lks. wide, course NW.; ascend 65 ft. over NE. slope.

38.43 The cor. of secs. 22, 23, 26 and 27.

Land, mountainous. Soil, stony clay. Timber, fir, cedar, hemlock, yew, maple and madrone; undergrowth, hazel, vinemaple, salal, madrone, poison oak and fir reproduction.

N. 1° 31' E., between secs. 22 and 23.

Descend 99 ft. over NE. slope, through heavy timber and dense undergrowth.

1.91 Abandoned skid road, 15 lks. wide, bears N. and S. 15° E.

2.82 Markham Creek, 4 lks. wide, course N. 70° W.; ascend 47 ft. over SW. slope.

3.97 Abandoned logging road, 15 lks. wide, bears NW. and S. 70° E.