

County Surveyor's Record, Douglas County, Oregon

26

Dependent Resurvey of Portion of Subdivisional Lines, T. 25 S., R. 4 W.

CHAINS

5.96	Spur, slopes N.; descend 64 ft. over NW. slope.
7.98	Creek, 2 lks. wide, course S. 70° W.; ascend 314 ft. over S. slope.
18.96	Enter logged area, edge bears E. and W.
19.75	Spur, slopes SW.; descend 5 ft. over NW. slope.
20.25	Point for the S 1/16 sec. cor. of secs. 22 and 23. Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked <div style="text-align: center;"> S 1/16 S 22 S 23 1957 </div> from which A cedar, 14 ins. diam., bears N. 6½° E., 59½ lks. dist., marked S 1/16 S23 BT. A fir, 15 ins. diam., bears N. 42½° W., 104 lks. dist., marked S 1/16 S22 BT. Descend 47 ft. over NW. slope.
24.68	Foot of descent, slopes W.; ascend 75 ft. over S. slope.
25.58	Abandoned logging road, 10 lks. wide, bears SW. and N. curving to NW.
31.38	Spur, slopes W.; also abandoned logging road, 10 lks. wide, bears E. and W.; descend 273 ft. over NW. slope.
32.75	Skid road, 10 lks. wide, bears NE. and S. 10° W.
34.02	Skid road, 10 lks. wide, bears E. and S. 80° W.
40.50	Point for the ¼ sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked <div style="text-align: center;"> T25S R4W ¼ S 22 S 23 1957 </div> from which A fir, 13 ins. diam., bears S. 49¼° E., 274 lks. dist., marked ¼ S23 BT. A fir, 9 ins. diam., bears S. 5½° W., 177 lks. dist., marked ¼ S22 BT. Descend 4 ft. over NW. slope.
40.72	Spring branch, 1 lk. wide, course W.; descend 13 ft. over NW. slope.
41.63	Creek, 1 lk. wide, course W.; ascend 72 ft. over SW. slope.
43.40	Skid road, 10 lks. wide, bears N. 70° W. and S. 70° E.
45.90	Spur, slopes W.; descend 66 ft. over NW. slope.
47.96	Woven wire fence, bears N. 80° W. and S. 80° E.
49.30	Skid road, 10 lks. wide, bears E. and W.