

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines, T. 25 S., R. 4 W.

CHAINS

A fir, 12 ins. diam., bears S. 20° W., 214 lks. dist., marked T25S R4W S28 BT.

Land, mountainous. Soil, stony clay. Timber, fir, cedar, madrone and maple; undergrowth, hazel, vinemaple, salal and fir reproduction.

From the corner of secs. 22, 23, 26 and 27.

N. 87° 25' W., between secs. 22 and 27.

Ascend 169 ft. over NE. slope, through heavy timber and dense undergrowth.

8.77 Top of ascent on NE. slope; descend 28 ft. along N. slope.

10.42 Head of ravine, course N. 10° E.; ascend 53 ft. over NE. slope.

12.00 Abandoned skid road, 10 lks. wide, bears N. 60° W. and SE.

13.64 Top of ascent on NE. slope; descend 11 ft. along N. slope.

14.31 Ravine, course NE.; asc. 214 ft. over E. slope changing to NE. slope.

26.63 Spur ridge, bears N. 15° E. and S. 20° E.; descend 222 ft. over W. slope changing to SW. slope.

29.95 Woven-wire fence, bears N. 30° W. and S. 30° E.

31.44 Graded dirt logging road, 20 lks. wide, bears NW. and SE.

38.06 The $\frac{1}{4}$ sec. cor. of secs. 22 and 27, perpetuated by the county surveyor from the original bearing trees in 1914, monumented with a $1\frac{1}{2}$ in. iron pipe, set flush with the ground; from which the county surveyor's bearing trees, as follows:

A sawed fir stump, 20 ins. diam., bears N. 22 $\frac{1}{2}$ ° W., 7 $\frac{1}{2}$ lks. dist., with a burned face and opened blaze; no scribe marks visible.

A fir snag, 30 ins. diam., bears S. 15 $\frac{1}{2}$ ° E., 32 $\frac{1}{2}$ lks. dist., with S and other faint scribe marks visible on partially opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked

T25S R4W

$\frac{1}{4}$ S 22
 $\frac{1}{4}$ S 27

1957

from which

A cedar, 7 ins. diam., bears N. 53° 45' E., 47 $\frac{1}{2}$ lks. dist., marked $\frac{1}{4}$ S22 BT.

A fir, 16 ins. diam., bears S. 24 $\frac{1}{2}$ ° W., 87 lks. dist., marked $\frac{1}{4}$ S27 BT.

Deposit old corner material alongside iron post.

N. 89° 22' W., beginning new measurement.

Descend 234 ft. over W. slope changing to SW. slope, through open area with scattering timber.

5.22 Enter reproduction, edge bears N. and S.