

County Surveyor's Record, Douglas County, Oregon

12523

65

Partial Subdivision of Section 13, T. 25 S. R. 4 W.

CHAINS 75.66	The $\frac{1}{4}$ sec. cor. of secs. 13 and 14. Land, rolling hills. Soil, rocky clay. Timber, E. $\frac{1}{2}$ mile, fir, maple, cedar, and madrone; W. $\frac{1}{2}$ mile logged. Undergrowth, poison oak, ocean spray, hazel, Oregon grape, salal, dogwood, vinemaple, and scattering manzanita and blackberry.
12.04	From the E $\frac{1}{16}$ sec. cor. of secs. 13 and 24. N. $0^{\circ} 42'$ W., on the N. and S. center line of the SE $\frac{1}{4}$ of sec. 13. Ascend 230 ft. over SE. slope changing to SW. slope, through heavy timber and dense undergrowth.
20.21	Spur, slopes W.; descend 182 ft. over NW. slope. Point for the SE $\frac{1}{16}$ sec. cor. of secs. 13 at intersection with the E. and W. center line of the SE $\frac{1}{4}$ of sec. 13. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked <div style="text-align: center;"> SE 1/16 S 13 1958 </div> from which A cedar, 17 ins. diam., bears S. 50° E., $3\frac{1}{2}$ lks. dist., marked SE 1/16 S13 BT. A cedar, 8 ins. diam., bears N. $71\frac{1}{2}^{\circ}$ W., $66\frac{1}{2}$ lks. dist., marked SE 1/16 S13 BT.
22.60	Descend 77 ft. over NW. slope. Foot of descent, slopes W.; ascend 213 ft. over SW. slope.
35.61	Ridge, bears E. and W.; descend 63 ft. over NE. slope.
40.49	The center E $\frac{1}{16}$ sec. cor. of sec. 13. <hr style="width: 20%; margin: 10px auto;"/> From the S $\frac{1}{16}$ sec. cor. of secs. 13 and 18 on E. bdy. of Tp. S. $87^{\circ} 54'$ W., on the E. and W. center line of the SE $\frac{1}{4}$ of sec. 13. Descend 270 ft. over SW. slope changing to broken NW. slope, through heavy timber and dense undergrowth.
18.915	The SE $\frac{1}{16}$ sec. cor. of sec. 13. Descend 90 ft. over broken NW. slope.
37.79	The center S $\frac{1}{16}$ sec. cor. of sec. 13.
GENERAL DESCRIPTION	
The portion of township 25 south, range 4 west, that was resurveyed lies about 7 miles east of the town of Sutherlin, Oregon, and is drained by tributaries of Calapocya Creek to the north and tributaries of the North Umpqua River to the south. The main divide between these two drainage systems lies in the southern tier of sections of the township and runs in a general east and west direction. Elevations range from 600 ft. above sea level to 2300 ft. above sea level.	