

County Surveyor's Record, <sup>7</sup>Douglas County, Oregon

Dependent Resurvey of a Portion of the East Boundary of T. 20 S., R. 8 W.

<p>CHAINS 13.34  29.19  35.55  38.74</p>	<p>Branch, 2 lks. wide, course S. 30° E.; asc. 430 ft. over S. slope.</p> <p>Ridge dividing North Sister Creek and South Sister Creek, bears N. 80° E. and SW.; desc. 153 ft. over NW. slope.</p> <p>Spur, slopes N. 50° W.; desc. 166 ft. over NE. slope, changing to N. slope.</p> <p>The cor. of secs. 1 and 12, determined at record bearing and distance from the remaining original bearing tree:</p> <p style="padding-left: 40px;">A fir snag, 50 ins. diam., bears N. 47° E., 38 lks. dist., marked with a healed blaze.</p> <p>At the corner point</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap marked</p> <div style="text-align: center;"> <table style="border-collapse: collapse; margin: auto;"> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">T 20 S</td> <td style="padding: 0 5px;"> </td> <td style="padding: 0 5px;">T 20 S</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 1</td> <td style="padding: 0 5px;"> </td> <td style="padding: 0 5px;">R 7 W</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 12</td> <td style="padding: 0 5px;"> </td> <td style="padding: 0 5px;">S 7</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">R 8 W</td> <td style="padding: 0 5px;"> </td> <td style="padding: 0 5px;"></td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;"></td> <td style="padding: 0 5px;"> </td> <td style="padding: 0 5px;">1954</td> </tr> </table> </div> <p>from which new bearing trees</p> <p style="padding-left: 40px;">A fir, 60 ins. diam., bears S. 87½° W., 37 lks. dist., marked T20S R8W S12 BT.</p> <p style="padding-left: 40px;">A fir, 60 ins. diam., bears N. 36½° W., 64 lks. dist., marked T20S R8W S1 BT.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, alder, chinquapin, dogwood, madrona, and cascara. Undergrowth, vine maple, hazel, huckleberry, slickleaf, arrowwood, and salal.</p> <hr/> <p>N. 1° 09' E., along the E. bdy. of sec. 1.</p> <p>Descend 142 ft. over broken N. slope, through heavy timber and dense undergrowth.</p> <p>3.94 North Sister Creek, 2 lks. wide, course W.; asc. 192 ft. over SW. slope.</p> <p>12.57 Branch, 1 lk. wide, course S. curving to S. 10° W.; asc. 44 ft. along creek.</p> <p>14.60 Leave creek, course SW. curving to S.; asc. 91 ft. over SE. slope, changing to SW. slope.</p> <p>17.62 The closing cor. of secs. 6 and 7, T. 20 S., R. 7 W., bears E., 22 lks. dist., monumented with a shattered sandstone, 11 x 11 ins., 4 ins. above ground, with no marks remaining, from which the original bearing trees:</p> <p style="padding-left: 40px;">A fir snag, 36 ins. diam., bears N. 60° E., 46 lks. dist., marked T20S R7W S6 BT. (Record distance, 55 lks.)</p> <p style="padding-left: 40px;">A fir, 48 ins. diam., bears S. 71° E., 73 lks. dist., marked with a healed blaze. (Record, S. 15½° E., 77 lks. dist.)</p> <p style="padding-left: 40px;">A fir, 34 ins. diam., bears N. 23° W., 23 lks. dist., marked with a healed blaze. (Record bearing, N. 13° W.)</p> <p>Ascend 272 ft. over SW. slope.</p>	T 20 S		T 20 S	S 1		R 7 W	S 12		S 7	R 8 W					1954
T 20 S		T 20 S														
S 1		R 7 W														
S 12		S 7														
R 8 W																
		1954														