

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the West Boundary of T. 20 S., R. 8 W.

CHAINS
41.24

Ridge, bears E. and W.; desc. 10 ft. over N. slope

41.69

The cor. of secs. 6 and 7, determined at record bearing and distance from the original bearing trees:

A fir snag, 70 ins. diam., bears N. 45° E., 71 lks. dist., with partial scribe marks visible on bark.

A fir snag, 76 ins. diam., bears S. 62° E., 30 lks. dist., with partial scribe marks visible on bark.

A fir snag, 50 ins. diam., bears S. 57° W., 32 lks. dist., marked T20S R9W S12 BT on bark.

A partially rotted fir stump, 12 ins. diam., bears N. 66° W., 18 lks. dist., with no remaining marks.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap marked

T 20 S	T 20 S
R 9 W	S 6
S 12	S 7
	R 8 W
	1953

from which new bearing trees

A hemlock, 8 ins. diam., bears N. 23½° E., 47 lks. dist., marked T20S R8W S6 BT.

A hemlock, 13 ins. diam., bears S. 22½° E., 22 lks. dist., marked T20S R8W S7 BT.

Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, maple, cedar, alder, chinquapin, dogwood, madrona, and cascara. Undergrowth, vine maple, hazel, huckleberry, slickleaf, arrowwood, and salal.

N. 0° 57' E., along the W. bdy. of sec. 6.

Descend 208 ft. over N. slope, through heavy timber and dense undergrowth.

- 3.05 Ravine, drains N. 50° W.; asc. 66 ft. over broken SE. slope.
- 12.00 Spur, slopes NW.; desc. 264 ft. over NE. slope.
- 17.45 Dry branch, 5 lks. wide, course N. 70° W.; asc. 83 ft. over SW. slope.
- 19.95 Top of ascent on W. slope; desc. 64 ft. along W. slope.
- 23.55 Dry branch, 6 lks. wide, course S. 55° W.; asc. 163 ft. over S. slope.
- 27.95 Spur ridge, bears N. 80° E. and S. 80° W.; desc. 111 ft. over NW. slope.
- 31.45 Head of ravine, drains N. 50° W.; desc. 6 ft. along W. slope.
- 32.80 Spur, slopes N. 80° W.; desc. 132 ft. over NW. slope.
- 36.00 Dry branch, 4 lks. wide, course S. 70° W.; asc. 70 ft. over S. slope.