

County Surveyor's Record, <sup>23</sup>Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines of T. 20 S., R. 8 W.

CHAINS

$\frac{1}{4} \frac{S 1}{S 12}$

1954

from which

A fir, 10 ins. diam., bears N. 37° E., 21 lks. dist., marked  $\frac{1}{4}$  S1 BT.

A fir, 12 ins. diam., bears S. 60 $\frac{1}{4}$ ° W., 21 lks. dist., marked  $\frac{1}{4}$  S12 BT.

Descend 2 ft. along S. slope.

- 40.02 Spur, slopes S. 15° W.; desc. 222 ft. over NW. slope, changing to W. slope.
- 45.54 Branch, 8 lks. wide, course S. 25° W.; asc. 340 ft. over NE. slope.
- 52.22 Spur, slopes S. 55° E.; desc. 64 ft. over SW. slope.
- 53.36 Draw, drains S. 5° E.; asc. 248 ft. over broken SE. slope.
- 68.01 Spur, slopes S. 15° W.; desc. 273 ft. over SW. slope.
- 74.54 Branch, 2 lks. wide, course S. 10° W.; asc. 160 ft. over SE. slope.
- 79.81 The cor. of secs. 1, 2, 11, and 12.

Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, alder, chinquapin, dogwood, madrona, and cascara. Undergrowth, vine maple, hazel, huckleberry, slickleaf, arrowwood, and salal.

N. 1° 20' E., bet. secs. 1 and 2.

Ascend 116 ft. over SE. slope, through heavy timber and dense undergrowth.

- 3.70 Spur, slopes S. 20° W.; asc. 273 ft. over SW. slope.
- 22.27 Spur ridge, bears N. 70° W. and SE.; desc. 369 ft. over N. slope.
- 31.49 Draw, drains S. 70° E.; asc. 280 ft. over SE. slope.
- 38.10 Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

$\frac{1}{4}$   
|  
S. 2 | S 1  
|  
1954

from which

A fir, 12 ins. diam., bears S. 41 $\frac{1}{2}$ ° E., 26 lks. dist., marked  $\frac{1}{4}$  S1 BT.

A fir, 18 ins. diam., bears S. 81 $\frac{1}{2}$ ° W., 11 lks. dist., marked  $\frac{1}{4}$  S2 BT.

The  $\frac{1}{4}$  sec. cor. falls on a spur, slopes S. 60° E.