

County Surveyor's Record, ³⁶Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines of T. 20 S., R. 8 W.

CHAINS	
9.10	South Sister Creek, 20 lks. wide, course W.; desc. slightly along creek.
10.35	Leave creek, course S. 75° W.; desc. 14 ft. over gentle W. slope.
19.50	Same road, bears N. 60° W. and S. 80° E.
21.90	South Sister Creek, 20 lks. wide, course NW. curving to W.; desc. slightly along creek.
25.00	Leave creek, course SW.; asc. 114 ft. over SE. slope.
28.00	Same road, bears N. 60° E. and S. 60° W.
36.30	Top of ascent on S. slope; desc. 18 ft. over SW. slope.
40.92	The $\frac{1}{4}$ sec. cor. of secs. 16 and 21, determined at record bearing and distance from the original bearing trees: <p style="margin-left: 40px;">A fir snag, 30 ins. diam., bears N. 80° E., 23 lks. dist., with marks $\frac{1}{4}$ remaining on bark.</p> <p style="margin-left: 40px;">A fir, 39 ins. diam., bears S. 70° E., 6 lks. dist., with marks $\frac{1}{4}$ S uncovered.</p> <p>At the corner point</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked</p> <div style="text-align: center; margin: 10px 0;"> $\frac{1}{4} \begin{array}{l} \text{S } 16 \\ \text{S } 21 \end{array}$ <p>1954</p> </div> <p>from which a new bearing tree</p> <p style="margin-left: 40px;">A fir, 38 ins. diam., bears N. 35° E., 36 lks. dist., marked $\frac{1}{4}$ S16 BT.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>S. 88° 14' W., beginning new measurement.</p> <p>Descend 112 ft. over SW. slope.</p>
10.50	South Sister Creek, 20 lks. wide, course N. 70° W.; asc. 116 ft. over NE. slope.
11.50	Same road, bears N. 70° W. and S. 70° E.
21.55	Top of ascent on N. slope; desc. 91 ft. along N. slope.
37.01	The cor. of secs. 16, 17, 20, and 21. <p style="margin-left: 40px;">Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, maple, cedar, alder, chinquapin, dogwood, madrona, and cascara. Undergrowth, vine maple, hazel, huckleberry, slickleaf, arrowwood, and salal.</p> <hr style="width: 80%; margin: 10px auto;"/> <p>N. 0° 07' W., bet. secs. 16 and 17.</p> <p>Descend 68 ft. over N. slope, through heavy timber and dense undergrowth.</p>
9.45	Unimproved road, bears E. and W.
10.45	South Sister Creek, 40 lks. wide, course S. 80° W.; asc. 57 ft. over SW. slope.