

County Surveyor's Record, Douglas County, Oregon
2

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 25 S., R. 7 W.

CHAINS

A cedar, 25 ins. diam., bears S. $43\frac{1}{4}^{\circ}$ W., 68 lks. dist., with scribe marks 14 25S R7W CS BT, visible on an unhealed blaze.

A cedar, 20 ins. diam., bears S. $15\frac{3}{4}^{\circ}$ W., 45 lks. dist., with scribe marks 25 7 S BT visible on an unhealed blaze.

A cedar, 20 ins. diam., bears N. 69° W., $41\frac{1}{2}$ lks. dist., with scribe marks 10 25 7W S BT visible on an unhealed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T25S R7W
S 10 | S 11
S 15 | S 14
1958

Deposit local corner material alongside iron post.

N. $0^{\circ} 27'$ E., bet. secs. 10 and 11, marking and blazing true line.

Descend 400 ft. over NE. slope, through scattering timber and dense undergrowth, along E. edge of logged area.

13.10 Bottle Creek, 5 lks. wide, course W.; asc. 256 ft. over S. slope.

14.42 Dirt logging road, 20 lks. wide, Bears N. 80° E. and W.

19.67 Point for S $1/16$ sec. cor. of secs. 10 and 11.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, to bedrock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

S $1/16$
S 10 | S 11
1958

from which

A white oak, 8 ins. diam., bears S. $77\frac{1}{2}^{\circ}$ E., 5 lks. dist., mkd. S $1/16$ S11 BT.

A white oak, 13 ins. diam., bears S. 42° W., 17 lks. dist., mkd. S $1/16$ S10 BT.

Ascend 241 ft. over SW. slope.

23.40 Skid road, 15 lks. wide, bears N. 30° E. and SW.; enter timber, edge bears N. 10° E. and W.

26.60 Spur, slopes SE.; asc. 16 ft. along general E. slope.

33.80 Ravine, course S. 30° E.; asc. 246 ft. over S. slope.

39.34 The $\frac{1}{4}$ sec. cor. of secs. 10 and 11, marked with the original madrone cor. tree, 17 ins. diam., no marks visible, from which the original bearing trees, as follows:

A madrone, 15 ins. diam., bears N. 30° E., 18 lks. dist., no marks visible.

A fallen and rotted oak, 13 ins. diam., the stump hole of which bears W., 13 lks. dist., I open a healed blaze on the fallen tree and find the overgrowth of scribe mark S and other illegible scribe marks.