

County Surveyor's Record, Douglas County, Oregon

T. 25 S., R. 7 W.

CHAINS

The main access to to the area is by Tyes Road, which is a county road paralleling the Umpqua River which has numerous logging roads extending from it into the northern portion of the township.

The only buildings noted within the area of resurvey is a cattle ranch located in section 10.

The soil consists of a rocky clay with a shallow overlay of humus and a steep bluff of exposed bedrock which parallels the north shore of the Umpqua River.

No evidence of mineral deposits was noted during the course of the resurvey.

The average of a considerably number of readings over all parts of the resurvey gives a value of $20^{\circ} 28'$ E. for the mean magnetic declination. There is a range of 38' in local attraction.