

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the N. Bdy., T. 27 S., R. 3 W.

CHAINS	
1.80	Dirt access road, 15 lks. wide, bears NE. and SW.
10.65	Foot of descent, slopes N.; asc. 158 ft. over NE. slope.
19.805	Point for the E 1/16 sec. cor. of secs. 4 and 33. Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> E 1/16 $\frac{S \ 33}{S \ 4}$ 1958 </div> from which A fir, 11 ins. diam., bears N. 29½° E., 49 lks. dist., mkd. E 1/16 S33 BT. A cedar, 9 ins. diam., bears S. 62° W., 52 lks. dist., mkd. E 1/16 S4 BT. Ascend 16 ft. over NE. slope.
21.20	Spur, slopes NE.; desc. 197 ft. over NW. slope.
30.80	Leave timber, enter logged and burned area, edge bears N. and S.
34.75	Creek, 3 lks. wide, course N.; asc. 103 ft. over NE. slope.
37.25	Spur, slopes N.; desc. 55 ft. over broken NW. slope.
39.61	Point for the ¼ sec. cor. of secs. 4 and 33, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 26 S R 3 W $\frac{1}{4} \frac{S \ 33}{S \ 4}$ T 27 S 1958 </div> from which A fir, 60 ins. diam., bears N. 75¾° W., 153 lks. dist., mkd. ¼ S33 BT. A cedar, 67 ins. diam., bears S. 48¾° W., 560 lks. dist., mkd. ¼ S4 BT. Descend 49 ft. over broken NW. slope.
43.90	Creek, 2 lks. wide, course NW.; desc. 13 ft. over NW. slope.
47.50	Foot of descent, slopes N.; asc. 70 ft. over NE. slope.
50.05	Spur, slopes N.; desc. 412 ft. over broken NW. slope.
57.85	Dirt access road, 15 lks. wide, bears NW. and SE.
79.22	The cor. of secs. 4, 5, 32, and 33, perpetuated with an iron pipe, ¾ in. diam., firmly set, 6 ins. above ground, and in a mound of stone, 2½ ft. base, 1 ft. high, from which the original bearing trees: A down and rotted black oak, 23 ins. diam., bears N. 69° E., 237 lks. dist., no scribe marks visible. (Record bearing N. 66° E.)