

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 27 S., R. 3 W.

CHAINS

T 27 S R 3 W
 S 10 | S 11
 S 15 | S 14
 1958

from which

A fir, 19 ins. diam., bears N. $41\frac{1}{2}^\circ$ E., 88 lks. dist.,
 mkd. T27S R3W S11 BT.

A fir, 12 ins. diam., bears S. 13° E., 78 lks. dist.,
 mkd. T27S R3W S14 BT.

A fir, 10 ins. diam., bears S. 11° W., 124 lks. dist.,
 mkd. T27S R3W S15 BT.

A fir, 13 ins. diam., bears N. $59\frac{1}{2}^\circ$ W., 58 lks. dist.,
 mkd. T27S R3W S10 BT.

N. $3^\circ 47'$ E., bet. secs. 10 and 11.

Ascend 14 ft. along E. slope, through heavy timber and dense under-
 growth.

4.90 Top of ascent, slopes E.; desc. 217 ft. over NE. slope.

16.50 Foot of descent, slopes NE.; asc. 60 ft. over SE. slope.

18.30 Spur, slopes NE.; desc. 142 ft. over broken NE. slope.

35.17 Spur, slopes NE.; desc. 134 ft. over NW. slope.

40.27 Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 11, at proportionate
 distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground,
 with brass cap mkd.

T 27 S R 3 W
 $\frac{1}{4}$
 S 10 | S 11
 1958

from which

A fir, 10 ins. diam., bears N. $59\frac{3}{4}^\circ$ E., 44 lks. dist.,
 mkd. $\frac{1}{4}$ S11 BT.

A fir, 7 ins. diam., bears S. 52° W., 66 lks. dist.,
 mkd. $\frac{1}{4}$ S10 BT.

Descend 183 ft. over NW. slope.

42.75 Leave timber, enter logged area, edge bears E. and W.

60.405 Point for the N 1/16 sec. cor. of secs. 10 and 11.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground,
 with brass cap mkd.

N 1/16
 S 10 | S 11
 1958

from which