

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 27 S., R. 3 W.

CHAINS Descend 188 ft. over NE. slope.

52.45 Abandoned dirt access road, 15 lks. wide, bears NW. curving to N. and SE. curving to S.

61.70 Foot of descent, slopes E.; asc. 198 ft. over SE. slope.

82.26 The corner of secs. 3, 4, 33, and 34, on the N. bdy. of the Tp.

Land, rolling hills.
Soil, rocky clay.
Timber, fir, cedar, madrone, and scattering pine; undergrowth, vinemaple, hazel, poison oak, salal, ocean spray, Oregon grape, and blackberry.

From the cor. of secs. 16, 17, 20, and 21, perpetuated and recorded by J. W. Byron, Deputy County Surveyor, in 1958, at record bearing and distance from the remains of the original bearing trees, monumented with an iron post, $\frac{3}{4}$ in. diam., firmly set, 8 ins. above ground, with brass cap mkd.

County Surveyors

T 27 S

S 17 | S 16

S 20 | S 21

R 3 W

Office 1958

from which the original bearing trees:

A chinquapin, 18 ins. diam., bears N. 35° E., 20 lks. dist., with scribe marks 16 BT visible on a partially opened blaze.

The stump hole of a hemlock, bears S. 55° E., 11 lks. dist.

and county surveyor's bearing trees:

A cedar, 22 ins. diam., bears N. 88° E., 71 lks. dist., mkd. T27S R3W S16 CS BT.

A hemlock, 14 ins. diam., bears S. 71° E., 39 lks. dist., mkd. T27S R3W S21 CS BT.

A cedar, 8 ins. diam., bears N. 30° W., 36 lks. dist., mkd. T27S R3W S17 CS BT.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 27 S R 3 W

S 17 | S 16

S 20 | S 21

1958

from which

A madrone, 21 ins. diam., bears N. 77 $\frac{1}{2}$ ° E., 99 lks. dist., mkd. T27S R3W S16 BT.

A cedar, 17 ins. diam., bears S. 8 $\frac{1}{2}$ ° E., 58 lks. dist., mkd. T27S R3W S21 BT.

A fir, 33 ins. diam., bears S. 39 $\frac{1}{2}$ ° W., 32 lks. dist., mkd. T27S R3W S20 BT.