

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 27 S., R. 3 W.

CHAINS

T 27 S R 3 W

S 9	S 10
S 16	S 15

1958

from which

A hemlock, 8 ins. diam., bears N. $69\frac{1}{4}^\circ$ E., 130 lks. dist., mkd. T27S R3W S10 BT.

A hemlock, 13 ins. diam., bears S. 42° E., 56 lks. dist., mkd. T27S R3W S15 BT.

A hemlock, 13 ins. diam., bears S. $18\frac{1}{2}^\circ$ W., 98 lks. dist., mkd. T27S R3W S16 BT.

A cedar, 25 ins. diam., bears N. 89° W., 95 lks. dist., mkd. T27S R3W S9 BT.

S. $89^\circ 24'$ W., bet. secs. 9 and 16.

Ascend 55 ft. over NE. slope, through heavy timber and scattering undergrowth.

- 0.80 Spur, slopes N.; desc. 32 ft. over NW. slope.
 - 4.65 Foot of descent, slopes N.; asc. 28 ft. over NE. slope.
 - 7.50 Spur, slopes N.; asc. 136 ft. over NE. slope.
 - 18.45 Top of ascent, slopes N.; also skid road, 15 lks. wide, bears N. and S.; desc. 394 ft. over NW. slope changing to W. slope.
 - 31.75 Jim Creek, 10 lks. wide, course NE.; asc. 74 ft. over SE. slope.
 - 34.70 Maintained dirt access road, 35 lks. wide, bears NE. and SW.
 - 39.545 Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 27 S R 3 W

$\frac{1}{4}$ S 9
S 16

1958

from which

A cedar, 16 ins. diam., bears N. 66° W., 18 lks. dist., mkd. $\frac{1}{4}$ S9 BT.

A fir, 9 ins. diam., bears S. 7° E., 58 lks. dist., mkd. $\frac{1}{4}$ S16 BT.

Ascend 112 ft. over SE. slope.

- 49.00 Top of ascent, slopes S.; desc. 13 ft. over SW. slope.
- 51.45 Ravine, drains SE.; asc. 149 ft. over SE. slope.
- 59.95 Top of ascent, slopes SW.; desc. 39 ft. over SW. slope.
- 64.80 Foot of descent, slopes SE.; asc. 286 ft. over SE. slope changing to NE. slope.

*FD OK 6/12/86
R. GEISLER
C.S. 63184*