

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 27 S., R. 3 W.

## CHAINS

- 6.70 Foot of descent, slopes S.; asc. 404 ft. over SE. slope.
- 33.15 Ridge, bears NE. and SW.; desc. 111 ft. over NW. slope.
- 40.02 The  $\frac{1}{4}$  sec. cor. of secs. 7 and 18, determined at record distance from the two original bearing trees:
- A fir, 40 ins. diam., bears N.  $85^\circ$  W., 78 lks. dist., bark scribed S and old axe marks.
- A rotted madrone snag, bears S.  $89^\circ$  E., 16 lks. dist., no marks visible. (Record bearing S.  $86^\circ$  E.)
- At the corner point
- Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the ground, with brass cap mkd.
- T 27 S R 3 W
- $\frac{1}{4}$   $\frac{S}{S}$   $\frac{7}{18}$
- 1958
- from which
- A cedar, 15 ins. diam., bears N.  $35\frac{1}{2}^\circ$  W., 145 lks. dist., mkd.  $\frac{1}{4}$  S7 BT.
- A fir, 33 ins. diam., bears S.  $6^\circ$  W., 87 lks. dist., mkd.  $\frac{1}{4}$  S18 BT.
- 
- S.  $88^\circ 58'$  W., beginning new measurement.
- Descend 102 ft. over NW. slope, through heavy timber and dense undergrowth.
- 9.10 Spur, slopes N.; desc. 225 ft. over NW. slope.
- 18.40 Dry creek, 15 lks. wide, course N.; asc. 590 ft. over NE. slope, changing to E. slope.
- 37.22 The cor. of secs. 7, 12, 13, and 18, on the W. bdy. of the Tp.
- Land, mountainous.  
Soil, rocky clay.  
Timber, fir, cedar, hemlock, madrone, and maple; undergrowth, salal, poison oak, vinemaple, ocean spray, hazel, and blackberry.
- 
- From the cor. of secs. 7, 8, 17, and 18.
- N.  $1^\circ 40'$  E., bet. secs. 7 and 8.
- Ascend 63 ft. over SE. slope, through heavy timber and dense undergrowth.
- 2.50 Top of ascent, slopes E.; desc. 158 ft. over NE. slope.
- 7.80 Foot of descent, slopes E.; asc. 17 ft. over SE. slope.
- 12.00 Ridge, bears NE. and SW.; desc. 156 ft. over NW. slope.
- 24.05 Foot of descent, slopes NE.; asc. 91 ft. over SE. slope.