

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines of T. 20 S., R. 9 W.

CHAINS

An alder, 16 ins. diam., bears S. 64° W., 46 lks. dist., with previously opened blaze now decayed.

A fir snag, 42 ins. diam., bears N. 50° W., 80 lks. dist., with no marks remaining. (Record, 180 lks. dist.)

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap marked

T 20 S R 9 W
S 22 | S 23
S 27 | S 26
 1953

from which new bearing trees,

An alder, 20 ins. diam., bears N. 9° E., 37 lks. dist., marked T20S R9W S23 BT.

A cedar, 20 ins. diam., bears S. 47° E., 50 lks. dist., marked T20S R9W S26 BT.

A cedar, 18 ins. diam., bears S. 4° W., 71 lks. dist., marked T20S R9W S27 BT.

An alder, 23 ins. diam., bears N. 52° W., 59 lks. dist., marked T20S R9W S22 BT.

Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, alder, and maple. Undergrowth, vine maple, evergreen huckleberry, hazel, salmonberry, red huckleberry, arrowwood, salal, Oregon grape, and sword fern.

From the cor. of secs. 23, 24, 25, and 26.

S. 88° 39' W., bet. secs. 23 and 26.

Descend 300 ft. over SW. slope, changing to W. slope, through heavy timber and dense undergrowth.

13.40 Coldwater Creek, 10 lks. wide, course S. 30° W.; asc. 170 ft. over SE. slope.

19.00 Spur, slopes S. 15° E.; desc. 40 ft. over SW. slope.

20.40 Ravine, course SE.; asc. 220 ft. over E. slope.

24.70 Spur ridge, bears NW. and SE.; desc. 80 ft. over SW. slope, changing to broken S. slope.

36.30 Ravine, course S.; asc. 70 ft. over E. slope.

39.80 Ridge, bears N. 60° E. and S. 30° W.; desc. 80 ft. over broken W. slope.

42.84 Point for the $\frac{1}{4}$ sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked

$\frac{1}{4}$ S 23
S 26
 1954

*FD OK by
 Les Roberts 2/27/84
 M 96-20*