

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. Bdy. of T. 21 S., R. 8 W.

CHAINS

T 21 S
R 8 W | R 7 W
S 36 | S 31
S 1 | S 6
T 22 S
1952

from which

A cedar, 10 ins. diam., bears N. $50\frac{1}{2}^{\circ}$ E., 43 lks. dist.,
marked T21S R7W S31 BT.

A cedar, 45 ins. diam., bears S. 30° E., 28 lks. dist.,
marked T22S R7W S6 BT.

A hemlock, 15 ins. diam., bears S. $34\frac{1}{2}^{\circ}$ W., 26 lks. dist.,
marked T22S R8W S1 BT.

A fir, 12 ins. diam., bears N. $42^{\circ} 45'$ W., 89 lks. dist.,
marked T21S R8W S36 BT.

N. $88^{\circ} 55'$ W., along the S. bdy. of sec. 36, marking and blazing the true line.

Ascend 196 ft. over NE. slope; through heavy timber and dense undergrowth.

5.75 Low spur, slopes NE.; desc. 21 ft. along N. slope.

9.20 Foot of descent, slopes N.; asc. 178 ft. over steep NE. slope.

13.20 Ridge, bears NW. and SE.; desc. 150 ft. over W. slope.

18.10 Foot of steep W. slope, bears NW. and SE.; desc. 69 ft. to $\frac{1}{4}$ sec. cor., along slightly broken S. slope.

30.25 Ravine, drains S. 25° E.

39.14 Point for the $\frac{1}{4}$ sec. cor. of sec. 36 only, determined from the remains of the original bearing trees:

A fir, 70 ins. diam., bears N. 40° E., 25 lks. dist.,
scribed $\frac{1}{4}$ S BT on bark.

A stump hole of a large fallen fir, bears S. 60° E.,
38 lks. dist.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground,
with brass cap marked

$\frac{1}{4}$ S 36
1952

from which

A fir, 52 ins. diam., bears N. 7° E., 46 lks. dist.,
marked $\frac{1}{4}$ S36 BT.

A hemlock, 7 ins. diam., bears N. $74^{\circ} 45'$ E., 57 lks. dist.,
marked $\frac{1}{4}$ S36 BT.

N. $89^{\circ} 30'$ W., beginning new measurement.

Descend 16 ft. along S. slope.

1.56 A fir, 70 ins. diam., on line, marked with two notches on E. and W. sides.