

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. Bdy. of T. 21 S., R. 8 W.

CHAINS
8.64

The closing cor. of secs. 1 and 2, T. 22 S., R. 8 W., bears South, 9 lks. dist., determined from the remaining original bearing tree, as follows:

A fir, 30 ins. diam., bears S. 20° W., 43 lks. dist., with scribe marks visible on nearly healed blaze.

At point on line

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap marked

T 21 S R 8 W
S 35
S 2 S 1
T 22 S R 8 W
C C
1952

*FD. OK 3/63
L. ROBERTS
M 94-6*

from which

A fir, 7 ins. diam., bears S. 77 $\frac{1}{4}$ ° E., 43 lks. dist., marked T22S R8W S1 CC BT. (New bearing tree).

A fir, 30 ins. diam., bears S. 16 $\frac{1}{2}$ ° W., 52 lks. dist., with scribe marks visible on nearly healed blaze (Old bearing tree)

A fir, 35 ins. diam., bears S. 74° W., 71 lks. dist., marked T22S R8W S22 CC BT. (New bearing tree).

Descend 24 ft. along S. slope.

- 9.30 Spur, slopes SW.; desc. 260 ft. over W. slope.
- 13.90 A sandstone ledge, 10 ft. high, bears N. and S., faces W.
- 14.80 Head of ravine, drains SW.; asc. slightly.
- 16.40 Low spur, slopes SW.; desc. 49 ft. over W. slope.
- 19.00 Spur, slopes SW.; desc. 58 ft. over NW. slope.
- 22.15 Ravine, drains SW., a little seepage water; desc. 188 ft. over broken SW. slope.
- 29.00 Branch, 2 lks. wide, course NW.; asc. 73 ft. over NE. slope.
- 33.30 Spur, slopes N.; desc. 256 ft. over W. slope, changing to NW. slope.
- 38.57 A hemlock, 22 ins. diam., on line, marked with two notches each on E. and W. sides.

39.32 Point for the $\frac{1}{4}$ sec. cor. of sec. 35 only, determined from the original bearing trees:

The stump hole of a fallen yew, bears N. 10° W., 20 lks. dist.

A yew, 12 ins. diam., bears S. 52° E., 27 lks. dist., with scribe marks visible on opened blaze.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 24 ins. in the ground, with brass cap marked

$\frac{1}{4}$ S 35
1952

*FD. OK 2/63
L. ROBERTS
M 94-6*