


County Surveyor's Record, Douglas County, Oregon  
20

Dependent Resurvey of a Portion of the Subdivisional Lines of T. 21 S., R. 8 W.

CHAINS  
36.95

Point for the  $\frac{1}{4}$  sec. cor. of secs. 23 and 24, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap marked



from which

A cedar, 22 ins. diam., bears N. 48° E., 17 lks. dist., marked  $\frac{1}{4}$  S24 BT.

A cedar, 18 ins. diam., bears N. 4 $\frac{1}{4}$ ° W., 88 lks. dist., marked  $\frac{1}{4}$  S23 BT.

Ascend 150 ft. along broken W. slope.

58.30 Branch, 5 lks. wide, course S. 20° W.; asc. 15 ft. along E. slope.

59.20 Branch, 2 lks. wide, course S. 70° E.; asc. 205 ft. over S. slope.

73.90 The cor. of secs. 13, 14, 23, and 24, determined from the original bearing trees, as follows:

A hemlock snag, 18 ins. diam., bears N. 25° E., 60 lks. dist., with partial scribe marks visible.


A dead and fallen hemlock, 12 ins. diam., bears S. 45° E., 30 lks. dist., with blaze healed.

A fir, 60 ins. diam., bears S. 75° W., 27 lks. dist., with no marks visible on burned blaze.

A fir, 55 ins. diam., bears N. 30° W., 27 lks. dist., with blaze healed.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap marked



from which new bearing trees,

A cedar, 25 ins. diam., bears N. 88° E., 58 lks. dist., marked T21S R8W S13 BT.

A hemlock, 26 ins. diam., bears S. 34° 45' E., 101 lks. dist., marked T21S R8W S24 BT.

A fir, 35 ins. diam., bears S. 42° W., 73 lks. dist., marked T21S R8W S23 BT.

Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, maple, and alder, partly burned. Undergrowth, vine maple, hazel, arrowwood, poison oak, and ceanothus, much of it thinned or removed by recent fire.