

County Surveyor's Record, Douglas County, Oregon

Subdivision of Sec. 31, T. 24 S., R. 3 W.

CHAINS
7.61

Top of ascent, slopes W.; desc. 118 ft. along W. slope, changing to NW. slope.

20.00

Farm access road, bears E. and W. and power line, bears N. 65° E. and S. 65° W.

20.40

Woven-wire fence, bears E. and W.

20.54

Point for the center S 1/16 sec. cor. of sec. 31.

The cor. point falls in a cultivated field, set an iron post, 28 ins. long, 2½ ins. diam., 12 ins. below the surface of the ground with brass cap mkd.

$$\begin{array}{c} C \\ | \\ S \ 1/16 \ | \ S \ 31 \\ | \\ C \\ 1958 \end{array}$$

from which

A fir, 20 ins. diam., bears N. 85¼° E., 316 lks. dist., mkd. CS 1/16 S31 BT.

A fir, 30 ins. diam., bears S. 81¼° W., 417½ lks. dist., mkd. CS 1/16 S31 BT.

From this point the NW. cor. of a wood frame dwelling bears S. 10° 43' E., 268½ lks. dist.

Descend 9 ft. over N. slope.

22.27

Weyerhaeuser Lumber Company railroad tracks, bear N. 60° E. and S. 60° W.

22.57

Telephone line, bears N. 60° E. and S. 60° W.

26.57

Leave cultivated field, edge bears NE. and SW.

27.66

Calapooya Creek, 80 lks. wide, course SW.; asc. 206 ft. over SE. slope.

28.86

Maintained, gravel surfaced road, bears N. 70° E. and S. 70° W.; enter old logged area, edge bears N. 70° E. and S. 70° W.; through scattering timber and dense undergrowth.

35.85

Spring branch, 1 lk. wide, course S. 10° E.; asc. 160 ft. over S. slope.

41.08

Point for the center ¼ sec. cor. of sec. 31, at intersection with the E. and W. center line.

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

$$C \ \frac{1}{4} \ S \ 31$$

1958

from which

A fir, 10 ins. diam., bears S. 72° E., 106 lks. dist., mkd. C¼ S31 BT.

A cedar, 15 ins. diam., bears S. 55½° W., 82 lks. dist., mkd. C¼ S31 BT.

Ascend 322 ft. over S. slope, changing to SE. slope; leave logged area, edge bears E. and W.; enter heavy timber and dense undergrowth.