

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points, T. 24 S., R. 8 W.

CHAINS

A hemlock, 10 ins. diam., bears N. 27° W., 40 lks. dist.,  
mkd. T24S R8W S2 BT.


The  $\frac{1}{4}$  sec. cor. of secs. 1 and 2, determined at record bearing  
and distance from the original bearing trees:

A cedar, 28 ins. diam., bears S. 15° E., 46 lks. dist.,  
with healed blaze.

A fir, 42 ins. diam., bears S. 44° W., 42 lks. dist.,  
with healed blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the  
ground, with brass cap mkd.



from which

A white fir, 7 ins. diam., bears S. 26° E., 49 lks. dist.,  
mkd.  $\frac{1}{4}$  S1 BT.

A white fir, 13 ins. diam., bears N.  $82\frac{1}{2}$ ° W., 43 lks. dist.,  
mkd.  $\frac{1}{4}$  S2 BT.

The cor. of secs. 26, 27, 34, and 35, determined at record bearing  
and distance from the remains of the original bearing trees:

A rotted chinquapin stump, bears N. 19° E., 27 lks. dist.


A fir snag, 50 ins. diam., bears S. 12° E., 26 lks. dist.,  
with healed blaze.

A fir snag, 45 ins. diam., bears S. 28° W., 31 lks. dist.,  
with healed blaze.

A fir, 20 ins. diam., bears N. 81° W., 68 lks. dist.,  
with healed blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the  
ground, with brass cap mkd.



from which

A hemlock, 9 ins. diam., bears N. 34° E., 33 lks. dist.,  
mkd. T24S R8W S26 BT.

A hemlock, 8 ins. diam., bears S. 76° E., 30 lks. dist.,  
mkd. T24S R8W S35 BT.

A hemlock, 6 ins. diam., bears S.  $13\frac{1}{2}$ ° W., 104 lks. dist.,  
mkd. T24S R8W S34 BT.