

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. Bdy., T. 23 S., R. 7 W.

CHAINS

(Restoring the 1881 survey by W. H. Byars)

From the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W.

N. 89°16' W., along the S. bdy. of sec. 36, marking and blazing the true line.

Ascend 61 ft. over S. slope.

25.92 Top of ascent on S. slope; desc. 187 ft. over SW. slope. Enter logged area, edge bears N. and S.

36.26 Gully, drains S. 45° E.; desc. 19 ft. along S. slope.

38.745 Point for the $\frac{1}{4}$ sec. cor. of sec. 36 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with brass cap mkd.

T 23 S R 7 W
$\frac{1}{4}$ S 36
1957

from which

A fir, 6 ins. diam., bears N. 66° E., 50 lks. dist., mkd. $\frac{1}{4}$ S36 BT.A fir, 6 ins. diam., bears N. 60° W., 80 lks. dist., mkd. $\frac{1}{4}$ S36 BT.

Descend 83 ft. over SW. slope.

46.88 Creek, 2 lks. wide, course S. 30° W.; asc. 47 ft. over SE. slope.

56.36 Spur, slopes S.; desc. 285 ft. along SW. slope.

70.42 Road, unimproved, 20 lks. wide, bears N. 25° E. and S. 25° W.

77.20 Road, unimproved, 25 lks. wide, bears N. and S.

77.49 The cor. of secs. 35 and 36 only, perpetuated and recorded by the County Surveyor, in 1955, at record bearing and distance from the only remaining original bearing tree, monumented with an iron pipe, 2 ins. diam., protruding 8 ins. above ground, firmly set, with brass cap mkd.

COUNTY SURVEYORS
T 23 S R 7 W
S 35 S 36
T 24 S R 7 W
1955
OFFICE

from which the original bearing tree

The easterly of a sawed, double fir stump, 20 ins. diam., bears N. 51° E., 71 lks. dist., with scribe marks BT visible on a partially opened blaze.

and County Surveyor's bearing tree

A fir, 40 ins. diam., bears N. 80° W., 33 lks. dist., mkd. T23S R7W S35 CS BT.

At the corner point