

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the 5th Stan. Par. S., N. Bdy. T. 23 S., R. 6 W.

CHAINS

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

C C
T22SR6W
S34 | S35
T23SR6W
S 3
1943

*FD. B.C. 6/92
J. BRANCH
M115-26
M115-23*

from which

A fir, 24 ins. diam., bears N. $12\frac{1}{4}^\circ$ E., 26 lks. dist., mkd. T22S R6W S35 CC BT.

A fir, 18 ins. diam., bears N. 56° W., 149 lks. dist., mkd. T22S R6W S34 CC BT.

Descend 120 ft. over NW. slope.

19.35 Creek, 5 lks. wide, course N. 15° W.; asc. 131 ft. over broken NE. slope.

27.35 Spring branch, 2 lks. wide, course N. 25° E.

40.34 The standard $\frac{1}{4}$ sec. cor. of sec. 3, the badly weathered and rotted remains of an old post, firmly set, with scribe marks visible and original bearing trees as follows:

A fir, 20 ins. diam., bears S. 28° E., 40 lks. dist., marks grown over.

A fir, 36 ins. diam., bears S. 72° W., 66 lks. dist., marks grown over.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$ S 3
S C
1943

*FD. B.C. 6/92
J. BRANCH
M115-26
M115-23*

Deposit the remains of the weathered stake alongside the iron post.

N. $89^\circ 49'$ W., beginning new measurement.

Ascend 6 ft. over NE. slope, through heavy timber and dense undergrowth.

1.00 Spur, slopes N.; desc. 68 ft. over NW. slope.

3.15 Creek, 2 lks. wide, course N. 10° W.; asc. 73 ft. over E. slope.

8.00 Spur, slopes NW.; desc. 41 ft. over SW. slope.

11.65 Ravine, drains N. 30° W.; asc. 39 ft. over NE. slope.

14.59 Spur, slopes SW.; desc. 92 ft. over NW. slope.

19.88 Creek, 3 lks. wide, course N. 10° W.; asc. 156 ft. over broken NE. slope.

22.70 Spur, slopes NW.; desc. 102 ft. over W. slope.

34.10 Creek, 4 lks. wide, course N. 60° E.; asc. 131 ft. over SE. slope.