

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the 5th Stan. Par. S., N. Bdy. T. 23 S., R. 6 W.

CHAINS
22.25

Top of ascent on S. slope; asc. 40 ft. along broken S. slope.

36.64

Creek, 2 lks. wide, course S. 10° E.; asc. 84 ft. over steep SE. slope.

38.47

The standard $\frac{1}{4}$ sec. cor. of sec. 4, monumented with a sandstone, 16 x 12 x 6 ins., firmly set, marked SC $\frac{1}{4}$ on S. face, from which the remains of the original bearing trees:A cedar stump, burned, 12 ins. diam., bears S. 44° E.,
19 lks. dist.A fir, 48 ins. diam., bears S. 50° W., 39 lks. dist.,
with a healed blaze.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 24 ins. in the ground,
and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

 $\frac{1}{4}$ S 4
 S C
 1955

N. 89°41' W., beginning new measurement.

Ascend 318 ft. over steep SE. slope.

7.28

Ridge, bears N. and S., trail bears N. and S.; desc. 208 ft. over
W. slope.

13.92

Creek, 2 lks. wide, course N.; asc. 177 ft. over E. slope.

20.85

Ridge, bears N. 10° W. and S. 10° E.; desc. 45 ft. over W. slope.

24.01

Trail, bears N. 60° W. and S. 45° E.; desc. 384 ft. over W. slope.

39.42

The standard cor. of secs. 4 and 5, monumented with a sandstone,
14 x 12 x 8 ins., firmly set, with 2 grooves on W. and 4 grooves on
E. faces, SC on S. face, from which the remains of the original
bearing trees:

A stump hole, bears S. 82° E., 159 lks. dist.

A stump, burned, bears S. 6 $\frac{1}{2}$ ° W., 180 lks. dist.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground,
and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

 T22SR6W
 S 33
 S 5 | S 4
 T23SR6W
 S C
 1955

from which

A fir, 18 ins. diam., bears S. 22 $\frac{1}{2}$ ° E., 44 lks. dist.,
mkd. T23S R6W S4 SC BT.A fir, 14 ins. diam., bears S. 33 $\frac{1}{2}$ ° W., 72 lks. dist.,
mkd. T23S R6W S5 SC BT.

Reset corner stone alongside the iron post, properly oriented.