

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the 5th Stan. Par. S., N. Bdy. T. 23 S., R. 6 W.

CHAINS

This corner falls in the bed of a ravine, drains SW.

Land, mountainous. Soil, sandy and rocky clay. Timber, fir, hemlock, and cedar. Undergrowth, poison oak, vine maple, salal, and alder.

S.  $89^{\circ}32'$  W., along the N. bdy. of sec. 5.

Ascend 13 ft. over SE. slope.

6.04 Spur, slopes S.  $65^{\circ}$  W.; desc. 98 ft. over NW. slope.

9.37 The closing cor. of secs. 32 and 33, T. 22 S., R. 6 W., determined at record bearing and distance from the original bearing trees:

A fir, 42 ins. diam., bears N.  $11\frac{1}{2}^{\circ}$  W., 74 lks. dist., with a healed blaze.

A fir, 48 ins. diam., bears N.  $48\frac{1}{2}^{\circ}$  E., 130 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with brass cap mkd.

C C  
T22SR6W  
S32 | S33  
S 5  
T23SR6W  
1955

from which

A fir, 14 ins. diam., bears N.  $46\frac{1}{2}^{\circ}$  W., 23 lks. dist., mkd. T22S R6W S32 CC BT.

A fir, 12 ins. diam., bears N.  $63\frac{1}{2}^{\circ}$  E., 35 lks. dist., mkd. T22S R6W S33 CC BT.

Descend 291 ft. over steep NW. slope.

17.83 Draw, drains N.; desc. 405 ft. along broken N. slope.

39.55 The standard  $\frac{1}{4}$  sec. cor. of sec. 5 only, monumented with a sandstone, 12 x 12 x 10 ins., firmly set, mkd. SC  $\frac{1}{4}$  on S. face, from which the remains of the original bearing trees:

A hemlock stump, bears S.  $25^{\circ}$  E., 34 lks. dist.

A maple stub, bears S.  $4^{\circ}$  W., 59 lks. dist.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$  S 5  
S C  
1955

from which

A fir, 18 ins. diam., bears S.  $20^{\circ}$  E., 48 lks. dist., mkd.  $\frac{1}{4}$  S5 SC BT.