

County Surveyor's Record, Douglas County, Oregon
15

Dependent Resurvey of the East Boundary, T. 23 S., R. 6 W.

CHAINS

An oak, 14 ins. diam., bears N. 82° W., 523 lks. dist., marks grown over.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

T23S
R6W R5W
S25 S30
S36 S31
1943

*Id OK
Ken Hoffine
M117-52
July 1993*

from which

A fir, 5 ins. diam., bears S. 23° E., 307 lks. dist., mkd. T23S R5W S31 BT.

An oak, 8 ins. diam., bears S. 61° W., 445 lks. dist., mkd. T23S R6W S36 BT.

Land, mountainous. Soil, sandy and rocky loam. Timber, fir, hemlock and cedar. Undergrowth, oak, salal, laurel, vine maple, and chinquapin.

N. 0°08' E., bet. secs. 25 and 30.

Ascend 70 ft. over SE. slope, through heavy timber and dense undergrowth.

11.45 Spur, slopes S. 70° E.; desc. 107 ft. over NE. slope.

19.53 Leave timber, edge bears E. and W.; enter field, edge bears E. and W.

27.15 Creek, 2 lks. wide, course S. 60° E.; asc. 176 ft. over SW. slope.

36.87 Fence, bears NW. and SE.; leave field, edge bears NW. and SE.; enter heavy timber and dense undergrowth, edge bears NW. and SE.

40.08 The $\frac{1}{4}$ sec. cor. of secs. 25 and 30, determined at record bearing and distance to the remains of the original bearing trees:

An oak snag, 24 ins. diam., bears N. 55° E., 59 lks. dist., marks rotted off.

An oak stump, 20 ins. diam., bears S. 87° W., 125 lks. dist., marks rotted off.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$
S 25 S 30
1943

from which

A fir, 22 ins. diam., bears N. 37° E., 30 lks. dist., mkd. $\frac{1}{4}$ S30 BT.

A fir, 20 ins. diam., bears N. 40 $\frac{1}{2}$ ° W., 48 lks. dist., mkd. $\frac{1}{4}$ S25 BT.

N. 0°35' E., beginning new measurement.