

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the East Boundary, T. 23 S., R. 6 W.

CHAINS																
	Ascend 286 ft. over SW. slope, changing to S. slope.															
20.80	Spur, slopes S. 60° E.; desc. 99 ft. over NE. slope.															
32.35	Ravine, course S. 70° E.; asc. 133 ft. over SE. slope.															
36.45	Spur, slopes S. 70° E.; desc. 41 ft. over NE. slope.															
39.95	The cor. of secs. 19, 24, 25, and 30, determined at record bearing and distance to the original bearing trees: <ul style="list-style-type: none"> A fir stump, 30 ins. diam., bears N. 14° E., 40 lks. dist., marks rotted off. A fir stump, 30 ins. diam., bears S. 19° E., 109 lks. dist., marks rotted off. A fir, 60 ins. diam., bears S. 66½° W., 112 lks. dist., mkd. BT. A fir stump, 36 ins. diam., bears N. 12½° W., 93 lks. dist., marks rotted off. <p>At the corner point</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr><td></td><td style="text-align: center;">T23S</td><td></td></tr> <tr><td style="text-align: center;">R6W</td><td style="border-left: 1px solid black; border-right: 1px solid black; text-align: center;">R5W</td><td></td></tr> <tr><td style="text-align: center;">S24</td><td style="border-left: 1px solid black; border-right: 1px solid black; text-align: center;">S19</td><td></td></tr> <tr><td style="text-align: center;">S25</td><td style="border-left: 1px solid black; border-right: 1px solid black; text-align: center;">S30</td><td></td></tr> <tr><td></td><td style="text-align: center;">1943</td><td></td></tr> </table> </div> <p>from which</p> <ul style="list-style-type: none"> A fir, 14 ins. diam., bears N. 32° E., 41 lks. dist., mkd. T23S R5W S19 BT. A fir, 18 ins. diam., bears S. 22° E., 46 lks. dist., mkd. T23S R5W S30 BT. A fir, 10 ins. diam., bears N. 43° W., 68 lks. dist., mkd. T23S R6W S24 BT. <p>Land, mountainous. Soil, sandy and rocky loam. Timber, fir, oak, and cedar. Undergrowth, salal, vine maple, alder, manzanita, laurel, huckleberry, and Oregon grape.</p>		T23S		R6W	R5W		S24	S19		S25	S30			1943	
	T23S															
R6W	R5W															
S24	S19															
S25	S30															
	1943															
	N. 0°19' E., bet. secs. 19 and 24.															
	Descend 10 ft. over NE. slope, through heavy timber and dense undergrowth.															
0.50	Ravine, course S. 70° E.; asc. 347 ft. over broken SE. slope.															
21.00	Trail, bears N. 45° E. and S. 45° W.															
21.10	Ridge, bears N. 45° E. and S. 45° W.; desc. 144 ft. over NW. slope.															
39.84	Point for the ¼ sec. cor. of secs. 19 and 24, at proportionate distance; there is no remaining evidence of the original corner. <p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with brass cap mkd.</p>															