

County Surveyor's Record, Douglas County, Oregon

17

Dependent Resurvey of the East Boundary, T. 23 S., R. 6 W.

CHAINS

$$\begin{array}{c} \frac{1}{4} \\ | \\ \text{S } 24 \text{ | S } 19 \\ | \\ 1943 \end{array}$$

from which

A fir, 40 ins. diam., bears S. 33° E., 67 lks. dist.,
mkd. $\frac{1}{4}$ S19 BT.

A fir, 36 ins. diam., bears N. 70° W., 144 lks. dist.,
mkd. $\frac{1}{4}$ S24 BT.

Over W. slope.

- 40.00 Ravine, course S. 70° W.; asc. 106 ft. over SW. slope.
- 47.70 Spur, slopes W.; desc. 83 ft. over NW. slope.
- 53.00 Ravine, course S. 70° W.; asc. 93 ft. over SW. slope.
- 59.08 Spur, slopes S. 70° W.; desc. 29 ft. over NW. slope.
- 62.25 Creek, 2 lks. wide, course S. 45° W.; asc. 247 ft. over S. slope.
- 68.80 Road, improved, bears NE. and SW.
- 72.55 Ridge, bears N. 80° W. and S. 80° E.; desc. 87 ft. over NW. slope.
- 79.68 Point for the cor. of secs. 13, 18, 19, and 24, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \text{T23S} \\ \text{R6W | R5W} \\ \text{S13 | S18} \\ \text{S24 | S19} \\ 1943 \end{array}$$

from which

A fir, 36 ins. diam., bears N. 39° E., 47 lks. dist.,
mkd. T23S R5W S18 BT.

A fir, 30 ins. diam., bears S. 66° E., 60 lks. dist.,
mkd. T23S R5W S19 BT.

A fir, 24 ins. diam., bears S. 45° W., 105 lks. dist.,
mkd. T23S R6W S24 BT.

A fir, 30 ins. diam., bears N. 38° W., 13 lks. dist.,
mkd. T23S R6W S13 BT.

Land, mountainous. Soil, sandy and rocky loam. Timber, fir, cedar, hemlock and oak. Undergrowth, salal, alder, vine maple, chinquapin, huckleberry, and blackberry.

N. 0°19' E., bet. secs. 13 and 18.

Descend 421 ft. over NW. slope, through heavy timber and dense undergrowth.