

County Surveyor's Record, Douglas County, Oregon

19

Dependent Resurvey of the East Boundary, T. 23 S., R. 6 W.

CHAINS

N. 0°19' E., bet. secs. 7 and 12.

Descend 137 ft. over NE. slope, changing to NW. slope.

26.60 Creek, 1 lk. wide, course N. 10° W.; desc. 156 ft. over NW. slope.

39.84 Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ | \\ \text{S } 12 \text{ | S } 7 \\ | \\ 1943 \end{array}$$

from which

A cedar, 8 ins. diam., bears N. 44° E., 33 lks. dist., mkd. $\frac{1}{4}$ S7 BT.A fir, 14 ins. diam., bears S. 33° W., 52 lks. dist., mkd. $\frac{1}{4}$ S12 BT.

Descend 14 ft. over NW. slope.

40.50 Creek, 2 lks. wide, course N. 20° E.; asc. 34 ft. over SE. slope.

44.00 Spur, slopes N. 20° E.; desc. 113 ft. over NW. slope.

51.40 Creek, 5 lks. wide, course N. 65° W.; asc. 127 ft. over SW. slope.

53.70 Road, unimproved, bears N. 45° W. and S. 45° E.

64.00 Spur, slopes W.; desc. 90 ft. over NW. slope.

67.00 Creek, 1 lk. wide, course S. 55° W.; asc. 312 ft. over SW. slope.

79.68 The cor. of secs. 1, 6, 7, and 12, determined at record bearings and distances from the remains of the original bearing trees:

A dead fir, 40 ins. diam., bears N. 40° E., 41 lks. dist., with marks burned off.

A fir stump, 24 ins. diam., bears S. 10° E., 32 lks. dist., with marks burned off.

A fir stump, 16 ins. diam., bears S. 45° W., 68 lks. dist., mkd. T23S S12 BT.

A fir stump, even with the ground, bears N. 5° W., 22 lks. dist.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \text{T23S} \\ \text{R6W | R5W} \\ \text{S } 1 \text{ | S } 6 \\ \text{S12 | S } 7 \\ 1943 \end{array}$$

from which

A fir, 40 ins. diam., bears N. 49° E., 49 lks. dist., mkd. T23S R5W S6 BT.