

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the South Boundary, T. 23 S., R. 6 W.

CHAINS

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

T23SR6W
S35 | S36
 S 2 | S 1
 T24S
 1943

from which

A fir, 22 ins. diam., bears N. $62\frac{1}{2}^{\circ}$ E., 98 lks. dist., mkd. T23S R6W S36 BT.

A fir, 20 ins. diam., bears S. $43\frac{1}{2}^{\circ}$ E., 26 lks. dist., mkd. T24S R6W S1 BT.

A fir, 30 ins. diam., bears S. $33\frac{1}{2}^{\circ}$ W., 32 lks. dist., mkd. T24S R6W S2 BT.

A fir, 30 ins. diam., bears N. 23° W., 74 lks. dist., mkd. T23S R6W S35 BT.

Land, mountainous. Soil, sandy and rocky loam. Timber, fir, cedar, and oak. Undergrowth, alder, vine maple, manzanita, laurel, madrone, poison oak, huckleberry, and fern.

N. $89^{\circ}50'$ W., bet. secs. 2 and 35.

Along S. slope, through heavy timber and dense undergrowth.

4.10 Creek, 1 lk. wide, course S. 70° E.; asc. 725 ft. over SE. slope, changing to E. slope.

28.74 Ridge, bears N. 20° E. and S. 20° W.; desc. 72 ft. over NW. slope.

39.97 Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$ S 35
 S 2
 1943

from which

A fir, 40 ins. diam., bears N. 19° E., 58 lks. dist., mkd. $\frac{1}{4}$ S35 BT.

A fir, 20 ins. diam., bears S. 24° W., 48 lks. dist., mkd. $\frac{1}{4}$ S2 BT.

Descend 292 ft. over NW. slope, changing to W. slope.

58.45 Creek, 3 lks. wide, course N. 20° W.; asc. 47 ft. over NE. slope.

61.65 Spur, slopes N.; desc. 325 ft. over NW. slope, changing to W. slope.

79.94 The cor. of secs. 2, 3, 34, and 35, a wooden stake, 30 ins. long, 6 ins. sq., firmly set, with scribe marks rotted off, and remains of the original bearing trees:

A dead and fallen fir, 30 ins. diam., bears N. 12° E., 31 lks. dist., marks rotted off.