

County Surveyor's Record, Douglas County, Oregon

27

Dependent Resurvey of the South Boundary, T. 23 S., R. 6 W.

CHAINS
18.37

Spur, slopes NE.; asc. 148 ft. over broken N. slope.

28.29

Spur, slopes NE.; desc. 144 ft. over NW. slope.

32.03

Creek, 2 lks. wide, course N, 10° E.; asc. 321 ft. over SE. slope.

38.12

Ridge, bears NW. and SE.; desc. 60 ft. over SW. slope.

40.48

The cor. of secs. 5, 6, 31, and 32, determined at record bearing and distance from the only remaining bearing tree:

A fir, 24 ins. diam., bears N. 22° E., 53 lks. dist.,
mkd. BT on open blaze.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T23SR6W
S31 | S32
S 6 | S 5
T24S
1957

from which

A hemlock, 12 ins. diam., bears S. 63° E., 35 lks. dist.,
mkd. T24S R6W S5 BT.

A hemlock, 8 ins. diam., bears S. 3° W., 17 lks. dist.,
mkd. T24S R6W S6 BT.

A fir, 30 ins. diam., bears N. 74° W., 57 lks. dist.,
mkd. T23S R6W S31 BT.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, blackberry, and poison oak.

S. 88°37' W., bet. secs. 6 and 31.

Descend 88 ft. over NW. slope.

4.64

Creek, 2 lks. wide, course N. 65° E.; asc. 788 ft. over NE. slope.

24.95

Ridge, bears N. 50° W. and S. 50° E.; desc. 294 ft. over SW. slope.

38.75

Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2 ins. diam., 10 ins. in the ground to solid rock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

T23SR6W
 $\frac{1}{4}$ S 31
S 6
T24S
1957

from which

A fir, 11 ins. diam., bears N. 39° W., 10 lks. dist.,
mkd. $\frac{1}{4}$ S31 BT.

A fir, 15 ins. diam., bears S. 65° W., 15 lks. dist.,
mkd. $\frac{1}{4}$ S6 BT.