

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the West Boundary, T. 23 S., R. 6 W.

CHAINS

from which

A fir, 8 ins. diam., bears N. 25° E., 27 lks. dist.,
mkd. $\frac{1}{4}$ S19 BT.

A fir, 10 ins. diam., bears S. 67° W., 10 lks. dist.,
mkd. $\frac{1}{4}$ S24 BT.

N. 0°24' W., beginning new measurement.

Ascend 246 ft. over SE. slope.

14.51 Ridge, bears N. 60° E. and S. 60° W.; desc. 456 ft. over N. slope, changing to NW. slope.

39.20 The cor. of secs. 13, 18, 19, and 24, determined at record bearing and distance from the remains of the original bearing trees:

A fir, 50 ins. diam., bears S. 45° W., 56 lks. dist.,
mkd. T23S R7W S24.

A cedar stump, burned, bears N. 58° W., 32 lks. dist.,
with healed blaze.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground,
with brass cap mkd.

T23S	
R7W	R6W
S13	S18
S24	S19
1957	

from which

A hemlock, 7 ins. diam., bears N. 47°30' E., 27 lks. dist.,
mkd. T23S R6W S18 BT.

A hemlock, 7 ins. diam., bears S. 22°30' E., 39 lks. dist.,
mkd. T23S R6W S19 BT.

A hemlock, 7 ins. diam., bears S. 88° W., 26 lks. dist.,
mkd. T23S R7W S24 BT.

A hemlock, 8 ins. diam., bears N. 45°30' W., 21 lks. dist.,
mkd. T23S R7W S13 BT.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, poison oak, blackberry, alder, madrone, and maple.

N. 0°04' E., bet. secs. 13 and 18.

Descend 83 ft. over N. slope.

2.50 Creek, 2 lks. wide, course N. 10° W., curving to W.; asc. 21 ft. over SW. slope, changing to W. slope.

7.63 Edge of bench, bears S. 70° E. and N. 70° W.; desc. 179 ft. over steep N. slope.

10.99 Creek, 8 lks. wide, course W.; asc. 229 ft. over SW. slope, changing to W. slope.

Fd OK.
D. by BAKER
Nov. 1982
M 93-23