

County Surveyor's Record, Douglas County, Oregon

12674

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

T23SR6W
S15 | S14
S22 | S23
 1957

from which

A fir, 6 ins. diam., bears N. 46° E., 38 lks. dist.,
 mkd. T23S R6W S14 BT.

A fir, 10 ins. diam., bears S. 43° E., 62 lks. dist.,
 mkd. T23S R6W S23 BT.

A chinquapin, 9 ins. diam., bears S. 56° W., 49 lks. dist.,
 mkd. T23S R6W S22 BT.

A fir, 13 ins. diam., bears N. 10° W., 65 lks. dist.,
 mkd. T23S R6W S15 BT.

Land, mountainous. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, and poison oak.

From the cor. of secs. 13, 14, 23, and 24.

S. 87°01' W., bet. secs. 14 and 23.

Ascend 86 ft. over NE. slope.

10.50 Road, improved, 20 lks. wide, bears N. 55° W. curving to N. 25° W. and S. 55° E. curving to S.; asc. 185 ft. over broken NE. slope.

20.85 Ridge, bears N. 30° W. and S. 30° E.; desc. 18 ft. over SW. slope.

23.30 Road, improved, 20 lks. wide, bears N. 15° W. and S. 15° E.; desc. 360 ft. over SW. slope changing to W. slope.

35.00 Creek, 2 lks. wide, course S. 20° E.; asc. 35 ft. over E. slope.

35.545 Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.

T23SR6W
 $\frac{1}{4}$ S 14
S 23
 1957

FS 04 495
 10871
 11-3

from which

A fir, 20 ins. diam., bears N. 17° E., 66 lks. dist.,
 mkd. $\frac{1}{4}$ S14 BT.

A fir, 12 ins. diam., bears S. 20° W., 30 lks. dist.,
 mkd. $\frac{1}{4}$ S23 BT.

Ascend 605 ft. over steep E. slope.

71.09 The cor. of secs. 14, 15, 22, and 23.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, vine maple, salal, poison oak, and salmonberry.

N. 3°31' W., bet. secs. 14 and 15.

Descend 30 ft. over NE. slope.