

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS
19.50

Ridge, bears N. 15° E. and S. 15° W.; desc. 550 ft. over NW. slope.

35.60

Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with brass cap mkd.

T23SR6W
 $\frac{1}{4}$ S 10
S 15
1957

from which

A fir, 7 ins. diam., bears N. 18 $\frac{1}{2}$ ° W., 32 lks. dist., mkd. $\frac{1}{4}$ S10 BT.

A hemlock, 6 ins. diam., bears S. 65 $\frac{1}{2}$ ° E., 41 lks. dist., mkd. $\frac{1}{4}$ S15 BT.

Descend 207 ft. over NW. slope.

52.50

Creek, 3 lks. wide, course N. 25° E.; asc. 407 ft. over NE. slope.

54.70

Road, unimproved, 10 lks. wide, bears N. 50° E. and S. 50° W.

71.20

The cor. of secs. 9, 10, 15, and 16.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, salmonberry, and madrone.

N. 1°56' W., bet. secs. 9 and 10.

Descend 203 ft. over NE. slope, changing to N. slope.

8.53

Road, improved, 30 lks. wide, bears S. 80° E. and W.; desc. 170 ft. over N. slope.

16.40

Creek, 3 lks. wide, course N. 80° E.; asc. 449 ft. over broken SE. slope.

34.36

Spur, slopes E.; desc. 162 ft. over NE. slope, changing to N. slope.

42.315

Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$
S9 | S10
1955

from which

A fir, 10 ins. diam., bears N. 38 $\frac{1}{2}$ ° E., 33 lks. dist., mkd. $\frac{1}{4}$ S10 BT.

A fir, 18 ins. diam., bears N. 71° W., 83 lks. dist., mkd. $\frac{1}{4}$ S9 BT.

Descend 230 ft. over N. slope.