

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS 49.80	Creek, 4 lks. wide, course S. 80° E.; asc. 462 ft. over S. slope.						
61.15	Spur, slopes S. 75° E.; desc. 248 ft. over broken NE. slope.						
79.85	Spur, slopes N. 80° E.; desc. 93 ft. over steep N. slope.						
81.40	Creek, 2 lks. wide, course N. 75° E.; asc. 79 ft. over SE. slope.						
84.63	<p>Point for the cor. of secs. 3, 4, 9, and 10, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T23SR6W</p> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 4</td> <td style="padding: 0 5px;">S 3</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 9</td> <td style="padding: 0 5px;">S 10</td> </tr> </table> <p>1955</p> </div> <p>from which</p> <p style="margin-left: 40px;">A cedar, 12 ins. diam., bears N. 51½° E., 34 lks. dist., mkd. T23S R6W S3 BT.</p> <p style="margin-left: 40px;">A cedar, 12 ins. diam., bears S. 65½° E., 46 lks. dist., mkd. T23S R6W S10 BT.</p> <p style="margin-left: 40px;">A dogwood, 16 ins. diam., bears S. 16½° W., 37 lks. dist., mkd. T23S R6W S9 BT.</p> <p style="margin-left: 40px;">A fir, 18 ins. diam., bears N. 7° W., 42 lks. dist., mkd. T23S R6W S4 BT.</p> <p>Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, poison oak, alder, and madrone.</p>	S 4	S 3	S 9	S 10		
S 4	S 3						
S 9	S 10						
<p>From the cor. of secs. 2, 3, 10, and 11.</p> <p>N. 86°14' W., bet. secs. 3 and 10.</p> <p>Descend 117 ft. over NW. slope, through dense undergrowth.</p>							
4.70	Creek, 7 lks. wide, course N. 70° E.; asc. 25 ft. over SE. slope.						
12.00	Road, improved, 16 lks. wide, bears N. 55° E. and S. 55° W.; asc. 132 ft. over SE. slope.						
21.42	Top of ascent on S. slope.						
31.70	Plank road, deteriorated, 15 lks. wide, bears S. 75° E. and N. 75° W.; desc. 7 ft. over brushy creek bottom.						
36.00	Creek, 10 lks. wide, course S. 80° E.						
36.385	<p>Point for the ¼ sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 5px;">¼</td> <td style="border-right: 1px solid black; padding: 0 5px;">S</td> <td style="padding: 0 5px;">3</td> </tr> <tr> <td></td> <td style="border-right: 1px solid black; padding: 0 5px;">S</td> <td style="padding: 0 5px;">10</td> </tr> </table> <p>1955</p> </div> <p>from which</p>	¼	S	3		S	10
¼	S	3					
	S	10					