

County Surveyor's Record, Douglas County, Oregon
 70

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

A fir, 47 ins. diam., bears N. $19\frac{1}{4}^\circ$ E., 23 lks. dist.,
 mkd. BT. I re-mark alongside T23S R6W S28 BT.
 (Record bearing and dist., N. 65° E., 15 lks.)

A fir, 45 ins. diam., bears S. 38° E., 100 lks. dist.,
 with a healed blaze. I re-mark alongside old blaze
 T23S R6W S33 BT. (Record bearing, S. 45° E.)

A fir, 55 ins. diam., bears S. 48° W., 13 lks. dist.,
 mkd. T23S R6W S32 BT. (Record bearing, S. 51° W.)

A fir, 45 ins. diam., bears N. $11\frac{3}{4}^\circ$ W., 45 lks. dist.,
 mkd. with a healed blaze. I re-marked alongside old
 blaze T23S R6W S29 BT. (Record bearing, N. 76° W.)

At the corner point

Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the
 ground, and in a mound of stone, 3 ft. base, to top, with brass
 cap mkd.

T23SR6W	
S29	S28
S32	S33
1957	

Land, mountainous. Soil, sandy loam, rock outcrops. Timber, fir,
 hemlock, and cedar. Undergrowth, salal, vine maple, poison oak,
 alder, madrone, and laurel.

From the cor. of secs. 27, 28, 33, and 34.

N. $87^\circ 44'$ W., bet. secs. 28 and 33.

Ascend 555 ft. over NE. slope.

14.47 Spur, slopes NE.; asc. 88 ft. over SE. slope.

19.53 Ridge, bears N. 60° W. and S. 60° E.; desc. 157 ft. over W. slope.

28.56 Ravine, drains N. 20° W.; asc. 31 ft. over NE. slope.

31.38 Spur, slopes N.; desc. 100 ft. over NW. slope.

35.67 Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 33, at proportionate
 distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 22 ins. in the ground,
 with brass cap mkd.

T23SR6W	
$\frac{1}{4}$ S 28	
$\frac{1}{4}$ S 33	
1957	

from which

A fir, 28 ins. diam., bears N. 74° W., 88 lks. dist.,
 mkd. $\frac{1}{4}$ S28 BT.

A fir, 26 ins. diam., bears S. 69° E., 123 lks. dist.,
 mkd. $\frac{1}{4}$ S33 BT.

Descend 49 ft. over NW. slope.

37.33 Gully, drains N. 15° W.; asc. 46 ft. over NE. slope.