


County Surveyor's Record, Douglas County, Oregon
74

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

T23SR6W



from which

A fir, 18 ins. diam., bears N. 42° E., 51 lks. dist.,
mkd. $\frac{1}{4}$ S21 BT.

A fir, 18 ins. diam., bears N. 50 $\frac{1}{2}$ ° W., 41 lks. dist.,
mkd. $\frac{1}{4}$ S20 BT.

Descend 447 ft. over NW. slope.

65.60 Gully, drains W.; asc. 70 ft. over N. slope.

68.26 Head of ravine, drains W.; desc. 296 ft. over NW. slope.

77.14 Creek, 10 lks. wide, course NE.; asc. 115 ft. over SE. slope.

81.09 The cor. of secs. 16, 17, 20, and 21, determined from two original bearing trees:


A fir, 26 ins. diam., dead and down, bears S. 41° E.,
37 lks. dist., mkd. S21 BT. (Record bearing and
dist., S. 20° E.)

A fir, 26 ins. diam., bears N. 20° W., 30 lks. dist.,
mkd. T23S R6W. (Record bearing, N. 70° W.)

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground,
and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T23SR6W



from which

✓ A fir, 25 ins. diam., bears N. 66 $\frac{1}{2}$ ° E., 17 lks. dist.,
mkd. T23S R6W S16 BT.

A cedar, 14 ins. diam., bears S. 52° E., 36 lks. dist.,
mkd. T23S R6W S21 BT.

A hemlock, 14 ins. diam., bears S. 69° W., 70 lks. dist.,
mkd. T23S R6W S20 BT.

A fir, 24 ins. diam., bears N. 27° W., 32 lks. dist.,
mkd. T23S R6W S17 BT.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and
cedar. Undergrowth, salal, poison oak, vine maple, alder, and
madrone.

From the cor. of secs. 15, 16, 21, and 22.

N. 87°45' W., bet. secs. 16 and 21.

Ascend 493 ft. over SE. slope, changing to E. slope.

13.70 Ridge, bears N. 20° W. and S. 20° E.; desc. 675 ft. over W. slope.