

County Surveyor's Record, Douglas County, Oregon

12696

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS
35.37

Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T23SR6W

$\frac{1}{4}$ S 16
S 21

1957

from which

A fir, 8 ins. diam., bears N., 28 lks. dist.,
mkd. $\frac{1}{4}$ S16 BT.

A fir, 6 ins. diam., bears S. $32\frac{1}{2}^\circ$ W., 80 lks. dist.,
mkd. $\frac{1}{4}$ S21 BT.

Descend 334 ft. over W. slope.

49.56 Creek, 2 lks. wide, course W.; desc. 173 ft. over W. slope.

58.00 Creek, 5 lks. wide, course N. 60° W.; asc. 40 ft. over NE. slope.

64.55 Spur, slopes N.; desc. 35 ft. over NW. slope.

67.75 Creek, 5 lks. wide, course N. 60° E.; asc. 156 ft. over SE. slope.

70.74 The cor. of secs. 16, 17, 20, and 21.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, salmonberry, and poison oak.

N. $15^\circ 20'$ W., bet. secs. 16 and 17.

Ascend 152 ft. over SE. slope.

7.72 Ravine, drains S. 50° E.; asc. 467 ft. over SW. slope.

18.86 Spur ridge, bears N. 73° E. and S. 73° W.; desc. 76 ft. over N. slope.

27.52 Head of ravine, drains E.; asc. 127 ft. along E. slope.

31.46 Ridge, bears N. 55° E. and S. 55° W.; desc. 259 ft. over N. slope.

36.76 Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T23SR6W

$\frac{1}{4}$
S17 | S16

1957

from which

A cedar, 18 ins. diam., bears S. 83° E., 32 lks. dist.,
mkd. $\frac{1}{4}$ S16 BT.